

NS/INC22000043/T1qc

ASS. REC. BY: TaufikREF: INC**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. MT/1156190-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Ms Loke Vehicle: IN / OUTVeh No: SHA 6935MYr Regn: 249, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota PriusC.C. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 237664

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STDKK3F4103090157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or not like

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 29/12/21Survey held at Confit Cozy

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

Frt n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/01/21 Taufikh finalised with Ms Loke LS \$2900, 2 days. (Red \$2169.74, 43%)

Date/Time, File Pass to?

☐

Preli. Report

1) 24/01 Typist☐

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ SI

Photos

Others

TOTAL

Report Format: TPLump Sum / H.B. / 2900

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SHA6935M

Date: 28/12/2021

Make : Toyota

Insurance: NTUC

Model : Prius

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT FENDER EMBLEM LH			\$86.50
1	FRT BUMPER SIDE GRILLE LH			\$85.10
1	FRONT BUMPER FOG LAMP LH			\$920.00
1	HEADLAMP LH			\$2,735.28
1	FRONT BUMPER COVER			\$499.90
1	FRONT BUMPER SIDE BRACKET LH			\$82.30
10	FRONT BUMPER CLIPS			\$22.00
1	FRT BUMPER CENTRE GRILLE			\$301.90
SUB TOTAL				\$4,732.98
LESS 25%				\$1,183.25
DISCOUNTED TOTAL				\$3,549.74
				\$-
Labour Charge				
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$600.00
	CHECK ALL LIGHTING			\$60.00
	TUFF KOTE			\$60.00
TOTAL LABOUR				\$1,520.00
ESTIMATE TOTAL				\$5,069.74

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749  
 WP' 28/12/21 @ 1620  
 43 Resurvey after repair  
 Tanpin@lkkauto.com  
 2-3 days

Date/Time: 28.12.2021 16:37

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4156881

JC NO 305499537

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
TEL (R) 65508755 (O)  
(P)


DISCOUNT CARD NO.

REGN NO. SHA6935M	MILEAGE
MAKE TOYOTA	FUEL E.....1/2.....
MODEL PRIUS HYBRID(G4A28.	DATE/TIME IN 12.2021 13:15
YR OF MANU. 13.12.2019	TARGET DATE
CHASSIS CODE JTDKB3FU103090157	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 28.12.2021  
NATURE: 3p 28.12.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

knowledge Slip

Exit Pass

me:

No.:

icle No.:

SHA6935M

YY

Vehicle No.:

SHA6935M

me of Service Advisor

Signature/Date

Name of Service Advisor

Date

be returned to Service Reception upon collection

To be kept by Security Guard