

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/CT/22000045/ups3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SJM4716E

at Workshop m/s

Lee brother

of

Insured:

CB 9888N

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

845k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3281

Date:

Person Contacted:

dep 6500

Vehicle: IN / OUT

Veh No:

SJM 4716E

Yr Regn:

05/01/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mazda 2

c.c

1498

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

175909

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMODE104180120674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/12/21

D.O.I.

31/1/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/screen shattered

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/1/22 informed AH node L/S & 6500

04-01-2029 MA & 18239

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SLK3455B

Not Adm
3/1/22
1/5 \$6500
5 days

ESTIMATE

DATE : 08.01.2022
VEHICLE NO : SJM4716E
MAKE/MODEL : MAZDA 2
ACC DATE : 31.12.2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	S\$	S\$
1	1 TAILGATE <i>Body 20</i>	1,199.00	1,199.00 ✓
2	1 TAILGATE GLASS <i>shattered</i>	896.50	896.50 ✓
3	1 TAILGATE WIPE ARM <i>Damaged</i>	68.60	68.60 ✓
4	1 TAILGATE WIPE MOTOR <i>Jim/Damaged</i>	341.20	341.20 ✓
5	1 TAILGATE LOGO <i>new</i>	52.70	52.70 ✓
6	1 TAILGATE EMBLEM ' MAZDA' <i>new</i>	42.30	42.30 ✓
7	1 TAILGATE EMBLEM '2' <i>new</i>	23.70	23.70 ✓
8	1 TAILGATE INNER LOCK <i>to/shift</i>	287.00	287.00 ✓
9	1 TAILGATE INNER PULL POCKET <i>new</i>	65.00	65.00 ✓
10	1 TAILGATE INNER TRIM <i>new</i>	192.60	192.60 ✓
11	10 TAILGATE INNER TRIM CLIPS <i>new</i>	4.50	45.00 ✓
12	2 TAILGATE STOPPER RH/LH <i>new</i>	12.60	25.20 ✓
13	2 TAILGATE DAMPER RH/LH <i>new</i>	181.20	362.40 ✓
14	1 TAILGATE OUTER PUSH SWITCH <i>new</i>	182.90	182.90 ✓
15	2 TAILLAMPS RH/LH <i>one</i>	587.00	1,174.00 ✓
16	2 TAILLAMPS PANELS RH/LH <i>R</i>	195.00	390.00 ✓
17	1 REAR BUMPER <i>new</i>	913.00	913.00 ✓
18	1 REAR BUMPER REINFORCEMENT <i>new</i>	365.00	365.00 ✓
19	2 REAR BUMPER SIDE RETAINERS RH/LH <i>new</i>	38.60	77.20 ✓
20	2 REAR BUMPER LOWER BRACKETS RH/LH <i>new</i>	68.50	137.00 ✓
21	1 REAR END PANEL <i>Body 20</i>	429.60	429.60 ✓
22	1 REAR END PANEL TRIM <i>new</i>	161.20	161.20 ✓
23	1 REAR EXHUAUST SILENCER <i>new</i>	592.00	592.00 ✓
24	1 REAR EXHUAUST CHROME PIPE <i>new</i>	112.00	112.00 ✓
25	1 REAR FLOOR BOARD <i>waged / torn</i>	386.00	386.00 ✓
26	1 REAR FLOOR PANEL <i>R</i>	715.00	715.00 ✓
27	2 REAR FENDER INNER TOP TRIMS RH/LH <i>new</i>	192.00	384.00 ✓
28	2 REAR FENDER INNER TRIM BOARD - LOWER <i>new</i>	482.00	964.00 ✓
29	2 REAR LICENCE LAMPS <i>345 x 2 = 690</i>	42.20	84.40 ✓
30	1 REAR SMART KEYLESS ANTENNA <i>new</i>	191.60	191.60 ✓
31	1 REAR SPEAKER BOARD <i>new</i>	391.60	391.60 ✓
			11,251.70
LESS 20%			2,250.34
			<u>9,001.36</u>

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
SPECIAL NETT ITEMS			
1	1 (SET) TAILGATE GLASS SEALANT <i>nee</i>	80.00	<i>40</i> 80.00
2	1 (SET) TAILGATE GLASS FOAM TAPE <i>nee</i>	65.00	<i>30</i> 65.00
3	1 TAILGATE GLASS SOLAR FILM <i>nee</i>	280.00	<i>150</i> 280.00
4	1 (SET) REAR BUMPER CLIP <i>nee</i>	60.00	<i>50</i> 60.00
5	1 (SET) REAR REVERSE SENSOR <i>shorted</i>	280.00	<i>200</i> 280.00
6	1 (SET) REAR NUMBER PLATE <i>su</i>	60.00	<i>x</i> 60.00
			<u>825.00</u>

LABOUR CHARGES :

1	TO TRANSFER & REINSTALL TAILGATE GLASS	<i>120</i>	180.00
2	TO CHECK REAR ELECTRICAL WIRING	<i>20</i>	80.00
3	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	<i>80</i>	120.00
4	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	<i>50</i>	80.00
5	TO TUFF KOTE	<i>60</i>	150.00
6	TO REMOVE & REPLACE EXHAUST SYSTEM	<i>11 x</i>	100.00
7	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	<i>1000</i>	1,300.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	<i>600</i>	1,500.00
TOTAL:			<u>3,330.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : **\$ 13,156.36**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-7229
202
p-5783-20
S.N-470
L-1930
8183.20
20%
6546.