

ASS. REC. BY:

REF:

11 / 220000 48/kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Transportation:

: S - R.S. - SI

: Fuel

: Others

TOTAL

Veh No:

SMR 5467

Yr Regn:

12, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy CHR

c.c

1797

Colour

M. Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

110846

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

84X10

2130684

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Inter-tac

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/1/2021

D.O.I.

3/1/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S 151

The UIC / Chassis frame / Body Structure affected due to collision.

Date: 03/01/2022
Vehicle No: SMR546T
Model: TOYOTA CHR HYBRID
Chassis: ZYX102130684-2018
Reg.Year: 2019

Not Authenitcal
Returning B4pam
4-5 days

Third Party Insurer: INDIA
Third Party Veh No: YM1961E
Date of Accident: 31/12/2021
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		<i>Cur</i> \$1,727.00
2	FRONT BUMPER	1		<i>CM</i> \$399.00
3	FRONT BUMPER SIDE BRACKET RH	1		<i>DIT</i> \$115.00
4	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		<i>MIT</i> \$88.00
5	FRONT BUMPER LOWER GRILLE	1		<i>Del/Ln</i> \$505.00
6	FRONT GRILLE	1		<i>Rn</i> \$173.00
7	FRONT FENDER RH	1		<i>Rn</i> \$826.00
8	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>Rn</i> \$65.00
9	FRONT FENDER INNER SHIELD RH	1		<i>CM</i> \$236.00
10	FRONT FENDER WHEEL ARCH GARNISH COVER RH	1		<i>MIT</i> \$143.00
11	FRONT RIM RH	1		<i>Rn</i> \$2,128.00
12	FRONT ABSORBER RH	1		\$493.00
13	FRONT LOWER ARM RH	1		\$760.00
14	FRONT KNUCKLE ARM RH	1		\$698.00
15	FRONT WHEEL BEARING RH	1		\$697.00
16	FRONT BONNET	1		REPAIR
SUB TOTAL				\$9,053.00
LESS 25%				-\$2,263.25
PARTS TOTAL				\$6,789.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Rn</i> \$50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>Rn</i> \$30.00
3	FRONT FENDER WHEEL ARCH COVER CLIPS RH	1		<i>Rn</i> \$30.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$700.00

400

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT BONNET & ETC.

\$700.00

600

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 03/01/2022
Vehicle No: SMR546T
Model: TOYOTA CHR HYBRID
Chassis: ZYX102130684-2018
Reg.Year: 2019

Third Party Insurer: INDIA
Third Party Veh No: YM1961E
Date of Accident: 31/12/2021
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM RH & ETC.	\$200.00	7
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	20%
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$120.00	7
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$100.00	20%
LABOUR TOTAL	\$1,900.00	

TING AN	TOTAL	\$8,799.75
---------	-------	------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Rung Chong Road Singapore 159143
Tel: (+65) 6472 1319 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

8B, 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

