

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/1088/2021/JT  
**DATE** : 4-Jan-22  
**WIP** : 61752

**VEHICLE NOT IN WORKSHOP. SURVEY TBC**

**YOUR INSURED VEH NO : SKK 410 L**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR TAY CHAI CHIN  
**ADDRESS** : 2 KENSINGTON PARK DRIVE  
#03-04 KENSINGTON PARK CONDO  
SINGAPORE 557320  
**TELEPHONE** : HP +65 97777838  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 5107156628-02  
**VEHICLE NO** : **SJA 1108 T**  
**MODEL CODE** : AUDI A3 SEDAN 1.4 TFSI  
**MODEL YEAR** : 16/2/2015  
**ENGINE NO** : CZC 298673  
**CHASSIS NO** : WAUZZZ8V1G1045709  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 31-Dec-21  
**PLACE OF ACCIDENT** : 2 KENSINGTON PARK DRIVE CAR PARK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 1108 T**

| S/N                         | NATURE OF JOBS  |          | ESTIMATED CHARGES  | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---|----------|--------------------|----------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.  | S/N \$   | 280.00             |                            |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$       | 1,400.00           |                            |
| 3                           | TO RESPRAY REAR BUMPER AND REAR END PANELLING.  | \$       | 2,000.00           |                            |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.  | S/N \$   | 192.00             |                            |
| <b>TOTAL LABOUR CHARGES</b> |   | <b>:</b> | <b>\$ 3,872.00</b> |                            |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1108 T**

|                             |   |            | <b>DAMAGED PARTS &amp; PRICES</b> |                 |
|-----------------------------|---|------------|-----------------------------------|-----------------|
| <b>S/N</b>                  | <b>PARTS DESCRIPTION</b>                  | <b>QTY</b> | <b>S/NETT</b>                     | <b>REMARKS</b>  |
| 1                           | REAR BUMPER                               | 1          | \$                                | 2,070.00        |
| 2                           | REAR BUMPER FIXING PARTS                  | 1          | \$                                | 193.00          |
| 3                           | REAR BUMPER GUIDE SECTION - LH / RH       | 2          | \$                                | 32.00           |
| 4                           | REAR BUMPER SPOILER                       | 1          | \$                                | 237.00          |
| 5                           | REAR LIGHT REFLECTOR - LH / RH            | 2          | \$                                | 82.00           |
| 6                           | REAR BUMPER REINFORCEMENT BEAM            | 1          | \$                                | 603.00          |
| 7                           | REAR BUMPER BRACKET - LH / RH             | 2          | \$                                | 26.00           |
| 8                           | REAR BUMPER GUIDE SECTION OUTER - LH / RH | 2          | \$                                | 134.00          |
| 9                           | REAR PARKING AID SENSOR - INNER / OUTER   | 2          |                                   | TBC             |
| 10                          | REAR PARKING AID SENSOR SEAL RING         | 4          | \$                                | 9.00            |
| 11                          | SUNDRIES                                  |            | \$                                | 300.00          |
| <b>TOTAL SPARE PARTS</b>    |   | <b>:</b>   | <b>\$</b>                         | <b>3,686.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |   | <b>:</b>   | <b>\$</b>                         | <b>3,872.00</b> |
| <b>GRAND TOTAL</b>          |   | <b>:</b>   | <b>\$</b>                         | <b>7,558.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT