



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1088/2021/JT
DATE : 4-Jan-22
WIP : 61752

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : SKK 410 L

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

11-Mar-22

OWNER'S NAME : MR TAY CHAI CHIN
ADDRESS : 2 KENSINGTON PARK DRIVE
#03-04 KENSINGTON PARK CONDO
SINGAPORE 557320
TELEPHONE : HP +65 97777838
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5107156628-02
VEHICLE NO : **SJA 1108 T**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 16/2/2015
ENGINE NO : CZC 298673
CHASSIS NO : WAUZZZ8V1G1045709
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Dec-21
PLACE OF ACCIDENT : 2 KENSINGTON PARK DRIVE CAR PARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 1108 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	\$ 500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	2,000.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,872.00	\$ 1,522.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1108 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,070.00	\$ 1,656.00
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	
4	REAR BUMPER SPOILER	1	\$ 237.00	\$ 189.60
5	REAR LIGHT REFLECTOR - LH / RH	2	\$ 82.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 603.00	
7	REAR BUMPER BRACKET - LH / RH	2	\$ 26.00	
8	REAR BUMPER GUIDE SECTION OUTER - LH / RH	2	\$ 134.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2	TBC	
10	REAR PARKING AID SENSOR SEAL RING	4	\$ 9.00	
11	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 3,686.00	\$ 1,845.60
TOTAL LABOUR CHARGES			\$ 3,872.00	\$ 1,522.00
GRAND TOTAL			\$ 7,558.00	\$ 3,367.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-25/02/22



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT