

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 3234Kat Workshop m/s Choo Motor

of _____

Insured: SLQ 2619X

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$69k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 474 831623Date / Time Action / Instruction Dep 12h.have video at folder here G.1411/1/22 4/5 @ 3800 informed AlanVeh No: SLR 3234K Yr Regn: 10/08/17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA1Make: Honda Freed Hybrid 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 105-495 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB71029971Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / 8 Rim / STD A/Rim orTyre Size: F: 195/60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 3/1/22D.O.I. 3/1/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)

) S + RS, SI

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

VEHICLE No: SLR 3234K

1PC	FRONT BUMPER	105.50
1PC	FRONT BUMPER BEAM	425
1PC	FRONT BUMPER LOWER GRILLE	
1PC	FRONT BUMPER TOW COVER	
2PCS	FRONT BUMPER SIDE RETAINERS @\$35.00	
1SET	FRONT BUMPER CLIPS	
1PC	FRONT GRILLE	690
1PC	FRONT GRILLE CHROME	
1PC	HEADLAMP LED O/S	1950.50
1PC	HEADLAMP LOWER BRACKET O/S	75.50
1PC	FRONT SUPPORT PANEL	
1PC	FRONT FENDER O/S	
1PC	WIPER WASHER TANK	
1PC	AIR CON CONDENSER	

DO	\$1,180.00	✓
Beif	\$455.00	✓
11	\$198.00	X
3u	\$45.00	X
ner	\$70.00	✓
nu	\$50.00	✓
cre	\$799.00	✓
11	\$620.00	X
cu	\$2,450.00	✓
cu	\$99.00	✓
R	\$688.00	X
2	\$615.00	X
2e	\$192.00	✓
11	\$988.00	X
	\$8,449.00	

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$80.00	X
11	\$100.00	X
	\$880.00	550
	\$800.00	600
TOTAL	\$10,359.00	

p- 4503
202
3602.40

LKK Auto Consultants: hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: