

ASS. REC. BY:

REF:

TH / 22000063/KC
GRB

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 832K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 20 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKN 7930R Yr Regn: 07 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c. 1591Colour: N. Red A/C: Insured / Std / NI / NASp. Reading: 270014 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM1H0H 41CM EU 240454Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 31/12/21D.O.I. 5/1/2022

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BT24/3 11 hrs 28000 Cals

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation: \$ + RS. \$

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKN7930R
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES2290011/YISHUN

Date: 05 Jan 2022

Policy No: 5088122164-05

Veh Reg No: SKN7930R

Make/Model: HYUNDAI HYUNDAI
ELANTRA 1.6AT ABS
D/AB 2WD 4DR

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 31/12/2021

TP Veh Reg No: SLK7140H

Chassis No: KMHDH41CMEU240454

Engine No: G4FGEU049848

Reg. Date: 18/07/2014

Estimate Repair Cost to Vehicle No :SKN7930R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	459.40	1 PC	459.40	✓
2 REAR BUMPER REINFORCEMENT	303.70	1 PC	303.70	✓
3 REAR BUMPER LOWER SKIRT	250.10	1 PC	250.10	✓
4 REAR BUMPER REFLECTORS	28.30	2 PCS	56.60	✓
5 REAR BUMPER SIDE RETAINERS	24.60	2 PCS	49.20	✓
6 REAR BUMPER CLIPS	3.00	6 PCS	18.00	✓
7 REAR BOOT	1,840.00	1 PC	1,840.00	✓
8 REAR BOOT INNER BOARD	84.80	1 PC	84.80	✓
9 REAR BOOT INNER SPONGE	198.10	1 PC	198.10	✓
10 REAR BOOT INNER LOCK	134.60	1 PC	134.60	✓
11 REAR BOOT INNER RUBBER	79.30	1 PC	79.30	508sn
12 REAR BOOT HINGES	94.30	2 PCS	188.60	✓
13 REAR FENDERS	1,856.60	2 PCS	3,713.20	✓
14 REAR FENDER INNER GARNISHS	171.70	2 PCS	343.40	✓
15 TAILLAMPS	388.00	2 PCS	776.00	✓
16 TAILLAMP PANELS	171.90	2 PCS	343.80	✓
17 REAR BOOT LOGO	28.10	1 PC	28.10	✓
18 REAR BOOT EMBLEM (ELANTRA)	48.80	1 PC	48.80	✓
19 REAR BOOT REFLECTORS	298.80	2 PCS	597.60	✓
20 REAR WINDSCREEN GLASS MOULDING	41.60	1 PC	41.60	✓
21 REAR SPARE TYRE COMPARTMENT	878.30	1 PC	878.30	✓
22 REAR SPARE TYRE TOP BOARD	213.80	1 PC	213.80	✓
23 REAR CENTRE PANEL	454.60	1 PC	454.60	✓
24 REAR CENTRE PANEL INNER TOP GARNISH	39.00	1 PC	39.00	✓
25 REAR AXLE	1,188.70	1 PC	1,188.70	✓
26 REAR RH WHEEL BEARING WITH HUB	352.90	1 PC	352.90	✓
27 REAR RH SHOCK ABSORBER	239.20	1 PC	239.20	✓
			12,921.40	
		Less 20%	2,584.28	10,337.12

Not Ashamed
1/1 Day &
Mercury After Paint
2 Days

B1

B1

B1/AU

CM

CM

Di

me

CM

CM

Di

Di/De

B1

Bu

Deform

CM

B1

me

me

me

CM

me

CM

B1

Di

Di

Di

Di

Di

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES2290011/YISHUN

Date: 05 Jan 2022

Policy No: 5088122164-05

Veh Reg No: SKN7930R

Make/Model: HYUNDAI HYUNDAI
ELANTRA 1.6AT ABS
D/AB 2WD 4DR

Chassis No: KMHDH41CMEU240454

Engine No: G4FGEU049848

Reg. Date: 18/07/2014

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 31/12/2021

TP Veh Reg No: SLK7140H

Estimate Repair Cost to Vehicle No :SKN7930R

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Special Net				
28 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
29 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
30 TOWING	100.00	1 LA	100.00	✓
31 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
32 PANEL BEATING	2,100.00	1 LA	2,100.00	2000
33 PUTTY & RESPRAY PAINTING	1,400.00	1 LA	1,400.00	1300
34 REMOVE & REFIX REAR UNDER CARRIAGE AND EXHAUST PIPE	280.00	1 LA	280.00	✓
35 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
36 RUSTPROOFING	100.00	1 LA	100.00	✓
			4,160.00	4,160.00
Total			S\$ 14,737.12	
Add GST @ 7%			1,031.60	
Total Amount Payable			S\$ 15,768.72	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE