

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8494U

01/01/22

MAKE REG 22.10.2019

CHIANG/AIG

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		Rp \$459.40
1	REAR BUMPER SIDE BRACKET RH		X \$55.80
1	REAR BUMPER REINFORCEMENT		? \$394.80
1	REAR BUMPER CENTRE MOULDING		de- \$451.25
1	REAR BUMPER TOW COVER		X \$94.60
1	REAR BUMPER REFLECTOR RH		X \$41.45
10	REAR BUMPER CLIPS		\$2.20 X \$22.00
	SUB TOTAL		\$1,519.30
	20.00%		\$303.86
	DISCOUNTED TOTAL		\$1,215.44
1	REAR REVERSE SENSOR		mm/ \$180.00
1	REAR BUMPER NUMBER PLAT W/HOLDER		am/ \$55.00
			\$235.00
	Labour Charge		
	Panel Beating		350 \$500.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		30 \$60.00
	Towing Fee		60 \$60.00
	Tuff Kote		X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,040.00
	ESTIMATE TOTAL		\$2,490.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9749 5749
 WP' 3/1/22 @ 5pm
 2 days
 1/1 Resurvey and parts
 Tanpin e lhauntan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.01.2022 12:45

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4158741

JC NO305500041

CUSTOMER

COMPANY COMFORT TRANSPORTATION PTE LTD

VEHICLE NO. 7010045

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

TEL (R) 65508755

(O)

(P)

SCOUT CARD NO.

REGN NO.

SHC8494U

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 01.01.2022 19:55

YR OF MANU.

22.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU186898

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 01.01.2022

NATURE: 3P 01.01.2022

3/NO

LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

1:

2:

Vehicle No.: SHC8494U

CHIANG

Vehicle No.:

SHC8494U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard