COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO

SHC8494U

MAKE

REG 22.10.2019

01/01/22

CHIANG/AIG

MODEL

IONIQ G3

MODEL	TORIQ 43			_
Qty	Parts Description/ Labour	Туре	Amount	
	1 REAR BUMPER			
	1 REAR BUMPER SIDE BRACKET RH		NN ★ \$55.80	
	1 REAR BUMPER REINFORCEMENT		XNN \$394.80	0
	1 REAR BUMPER CENTRE MOULDING		\$451.25	5
	1 REAR BUMPER TOW COVER		NNK \$94.60	0
	1 REAR BUMPER REFLECTOR RH		NNX \$41.4	5
	10 REAR BUMPER CLIPS		\$2.20 [4] \$22.0	0
	SUB TOTAL		\$1,519.3	
	20.00%		\$303.8	₆ 378.60
	DISCOUNTED TOTAL		\$1,215.4	4
	1 REAR REVERSE SENSOR 1 REAR BUMPER NUMBER PLAT W/HOLDER		\$180.00 \$55.00 \$235.0	0
	Labour Charge			-
	Panel Beating		250 \$500.0	o
	Spray Painting Charge		250 \$300.0	О
	Check Lighting and Wiring		3 \$60.0	0
	Towing Fee		\$60.0	0
	Tuff Kote		NN × \$60.0	О
	Remove/refix Reverse sensor		3 \$60.0	0
	TOTAL LABOUR		\$1,040.0	720
	ESTIMATE TOTAL		\$2,490.4	
L				\$1333.60
ſ	This is an initial estimate based on a visual inspection of the	above v	ehicle. The final repair quantum will	2 DAYS #
	be prepared after the vehicle is surveyed by a motor Survey	or appoi	nted by the insurance company.	

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Date/Time: 03.01.2022 12:45 Page : 1 JOB CARD Sales Order: 4158741 ream: ARC Repair TP(CLSO)1 JC NO305500041 REGN NO. SHC8494U **JSTOMER** MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE: HYUNDAI 3/MS FUEL ISTOMER NO. 7010045
DRESS 383 SIN MING DRIVE 7010045 E.....1/2... MODEL IONIQ(G3) DATE/TIME IN 01.2022 19:55 Singapore SINGAPORE 575717 65508755 L. (R) YR OF MANU. 22.10.2019 TARGET DATE (P) CHASSIS CODE KMHC851CVLU186898 COMPLETION DATE/TIME: 3COUNT CARD NO. JOB DESCRIPTION Accident Date: 01.01.2022 VATURE: 3P 01.01.2022 \ FRONT 3/NO LABOR CODE DESCRIPTION ECKED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE owledgement Slip Exit Pass 2.. Vehicle No.: CHIANG SHC8494U SHC8494U le No .: of Service Advisor Signature/Date Name of Service Adviso returned to Service Reception upon collection To be kept by Security Guard