



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22000070/Ktf3n2 Date: 10/01/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 7059U	Veh. Inspected	SHC 5132J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2200017/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/01/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTDKB3FU603092289	Colour	M.P.WHITE / RED
Odometer	118276 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	8 mm
L/H Front Tyre	195/65 R15	SAILUN	8 mm
R/H Rear Tyre	195/65 R15	SAILUN	8 mm
L/H Rear Tyre	195/65 R15	SAILUN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/12/2021	Inspection Date	04/01/2022
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1.500 Working Days	