

*Not Authorised
 Recovery B&P
 2600.88*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

AAD2201-012

SHC5132J

Vehicle No.:		SHC5132J
Chassis No.:	04 JAN 2022	JTDCB3FU603092289
Vehicle Make:		TOYOTA
Vehicle Model:		PRIUS GEN 4
Date of Accident :		31/12/2021
Third Party Insurer :		SOMPO
Date of Registration:		16/10/2020

PART		LIST
1 COVER, REAR BUMPER	\$	<i>R</i> 485.60 X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i> 332.70 X
1 COVER, REAR BUMPER, LOWER	\$	<i>Sm</i> 22.00 X
1 GUARD, REAR BUMPER, CENTER	\$	<i>nd/lw</i> 374.50 ✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>Ph</i> 132.60 X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sm</i> 132.60 X
1 COVER, DECK TRIM, REAR	\$	<i>Ph</i> 126.70 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00 X
TOTAL	\$	2,257.70
25%	\$	564.43
	\$	1,693.28

Special Nett

1SET PARKING AID	\$	<i>Sm</i> 700.00 X
1SET REAR BUMPER CLIP	\$	<i>na</i> 95.00 X
1 REAR BUMPER PROTECTOR	\$	<i>Sm</i> 180.00 X
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i> 85.00 X
1 END PANEL TRIM CLIP	\$	<i>na</i> 65.00 X
TOTAL	\$	1,125.00

TOTAL PARTS \$ 2,818.28

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 300.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5132J**AAD2201-012**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	100
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Towing Fees	\$	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	220
To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X

ns-cab Auto Services Pte Ltd

AAD2201-012

2 Ang Mo Kio Street 63 Singapore 569111

No. : 6287 6666 Fax No. : 6257 1330

GST Reg. No. 201019626G

5132J

To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	42	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	5	220.00	X
To replace, refix and top up coolant for radiator	\$	5	170.00	X
To lift-up / out engine with gear box and refit.	\$	4	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	6	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	5	380.00	X
TOTAL	\$		10,290.00	
Over All Total	\$		13,108.28	

(PART-BY-PART) Repair Days

25 DAYS

1 1/2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: