



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22000078/Vvf3n2	
			Date: 24/04/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1026P	Veh. Inspected	SDX 938X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/21/2079	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	04/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104545259	Colour	GREY
	Odometer	151829 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	TOURADOR	6 mm
	L/H Front Tyre	205/55 R16	TOURADOR	6 mm
	R/H Rear Tyre	205/55 R16	TOURADOR	6 mm
	L/H Rear Tyre	205/55 R16	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/12/2021	Inspection Date	14/03/2022
	Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	