

13/04/1978
43 YEARS AND 8 MONTHS
Male
(Phone) +65-96688627
(Home) +65-96688627
SINGAPORE 408611



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Loo Chee Hian
	Document No. 0	74 Tampines Road
	Document Date 03/01/2022	Singapore 535099
		Mobile: 96688627

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	18/03/2016	SDX0938X	0	21509	67/DS/SDX0938X
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104545259	1ZRX551416	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SHB1026P ACC DATE:31/12/2021 DRIVE IN:03/01/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING				72.00
3	S	BP-SUBLET CONDUCT FULL WHEEL ALIGNMENT				180.00
4	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE SENSOR				180.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
6	B	BP-LAB2 REPAIR & REALIGN RH REAR ACCIDENT AFFECTED AREAS				2160.00
7	B	BP-RES2 RESPRAY JOB ON RH REAR ACCIDENT AFFECTED AREAS				2360.00
8	1	S67003-02430 PANEL ASSY,RR DR RH	1.00	1323.00		1323.00
9	2	S61601-02270 PANEL SUB-ASSY, QUAR	1.00	1218.20		1218.20
10	3	K52159-0Z904 COVER, RR BUMPER	1.00	589.50		589.50
11	4	S52575-02140 RETAINER,RR BUMPER R	1.00	116.00		116.00
12	5	S52591-02301 SEAL, RR BUMPER SIDE	1.00	58.50		58.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Material fact
of the insu
Insurance
nd to copi



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no 6631 1188

ESTIMATE

Account Details		Customer Details	
THIRD PARTY CLAIM	Account No	Mr Loo Chee Hian 74 Tampines Road Singapore 535099 Mobile: 96688627	
	S1000020 / TPCLAIM		
	Document No		
	0		
	Document Date		
	03/01/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZRE171R	GEXGKZ S2	18/03/2016	SDX0938X	0	21509	67/DS/SDX0938X
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104545259		1ZRX551416	60	Sam San Joi	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
13	6	S52161-0K040	CLIPS	1.00	4.30		4.30
14	7	S42611-02C80	WHEEL,DISC	1.00	2133.00		2133.00
Therevan @ Lkhauto. com 82235769 P/P b4r part 5 days w/p 14/3/22 1200 LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:							

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts	5,442.50	GST 7.00%	742.32
				Labour	4,730.00	Less	0.00
				Sublet	432.00		
				Lubrication/Fluid	0.00		
				Others	0.00	Amount Due	11,346.82

Customer Copy