

PRECISE AUTO SERVICE
NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883
TEL : 6745 7367 FAX : 6841 3390
CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Confirmation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10-02-22

Date of Accident : 30-12-2021
 Our Ref No. : YN 5174D/T/21

CREMELAND PTE LTD
 Blk 1007 Aljunied Ave 4
 #01-17
 Singapore 389908

LKK - Mercedes
 Date Input: 12/01/22 to 19/01/22

with Approval
 12/1/22
 2/5 \$2700
 5 days

ESTIMATE BILL ON VEH. NO. : YN 5174D
MODEL : MITSUBISHI FUSO
CHASSIS NO : FEB21EA30436

1st item

NETT ITEM

Tail Lamp - LH	230.91	✓
Tail Lamp Bracket	98.00	✓
Rear End Panel	867.10	✓
Rear End Panel Rubber Stopper - LH	120.00	✓
Rear End Panel Stopper Bracket	90.00	✓
	<u>1,406.01</u>	
	Less Discount 10%:	<u>140.60</u>
		<u>1,265.41</u>

SPECIAL NETT ITEM

Rear Bumper	1,200.00	✓
Rear Bumper Bracket	300.00	✓
Rear Step Bracket	550.00	✓
60 Km/h Sticker	15.00	✓
To Tuff Coat Affected Areas.	180.00	✓
To Check and Reconnect Tail Lamp Wiring & Reverse Camera Wiring.	120.00	✓
To Respray Affected Areas.	900.00	✓
To Renew Damaged Parts, Straighten & Repair Rear LH Swing Door & Aligned All Parts.	1,000.00	✓

LABOUR CHARGE

5,530.41
 GST 7%: 387.13
TOTAL AMOUNT: 5,917.54

P-1406.01
 25%
 P-1054.50
 S.N-1210
 L-1160