



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2206852
3 ANSON ROAD #16-00	INV Date	04/11/2022
SPRINGLEAF TOWER	Reference	CC3/CTI22000084/Tpa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SHC 8968U
Insured Veh.	SMV 2683X
Claim No.	SNM21D207697/C02/TANKL
Policy No.	DMPCSNW00173452100
Accident Date	30/12/2021
Inspection Date	03/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC3/CTI22000084/Tpa3q2 Date: 04/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMV 2683X	Veh. Inspected	SHC 8968U
Policy No.	DMPCSNW00173452100	Coverage (\$)	0.00
Claim No.	SNM21D207697/C02/TANKL	Excess (\$)	0.00
Assign From		Assign Date	03/01/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU086928	Colour	BLUE
Odometer	697855 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/12/2021	Inspection Date	03/01/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8968U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	228.00	-
	LESS 20% DISCOUNT		-371.12	-225.60
			1,484.48	902.40
SPECIAL NETT ITEMS				
1	BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			230.00	50.00
LABOUR				
	PANEL BEATING.		500.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			980.00	560.00
GRAND TOTAL			2,694.48	1,512.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC3/CT122000084/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8968U

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8968U

RE-INSPECTION

