

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8968U
 MAKE 07/04/16
 MODEL HYU- I40

30.12.21

CHIANG/ CHINA

Qty	Parts Description/ Labour	TYPE	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
	SUB TOTAL			\$1,855.60
	20.00% DISCOUNTED TOTAL			\$371.12
				\$1,484.48
1	BUMPERRUBBER MAT			\$50.00
1	REVERSE SENSOR			\$180.00
				\$185.70
	Labour Charge			
	Panel Beating			\$500.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$980.00
	ESTIMATE TOTAL			\$2,650.18

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanpin 97495749
 'wp' 2/5 resurvey after repair
 3/1/22 @ Spr
 2 days tanpin@hant.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305499975


CUSTOMER
CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R): 65508755 (O)
TEL (P):
COUNT CARD NO.

REGN NO: SHC8968U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 03.01.2022 09:45
YR OF MANU: 07.04.2016	TARGET DATE
CHASSIS CODE: KMHLB41UMGU086928	COMPLETION DATE/TIME:

Accident Date: 30.12.2021
NATURE: 3P 30.12.2021

JOB DESCRIPTION

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHC8968U** **CHIANG**

Vehicle No.: **SHC8968U**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard