

**AIR ESTIMATE\***

VEHICLE NO SHC8968U  
 MAKE 07/04/16  
 MODEL HYU- I40

30.12.21

CHIANG/ CHINA

| Qty | Parts Description/ Labour      | TYPE | Unit Price                | Amount     |
|-----|--------------------------------|------|---------------------------|------------|
| 1   | REAR BUMPER COVER              |      |                           | \$1,106.00 |
| 2   | REAR BUMPER BRACKET SIDE LH/RH |      | \$35.60                   | \$71.20    |
| 10  | REAR BUMPER CLIPS              |      | \$2.20                    | \$22.00    |
| 1   | REAR BUMPER REINFORCEMENT      |      |                           | \$428.40   |
| 1   | REAR BUMPER UNDER COVER        |      |                           | \$228.00   |
|     | <b>SUB TOTAL</b>               |      |                           | \$1,855.60 |
|     | 20.00%                         |      | 1128                      | \$371.12   |
|     | <b>DISCOUNTED TOTAL</b>        |      | 902.40                    | \$1,484.48 |
| 1   | BUMPERRUBBER MAT               |      |                           | \$50.00    |
| 1   | REVERSE SENSOR                 |      | 50                        | \$180.00   |
|     |                                |      |                           | \$185.70   |
|     | <b>Labour Charge</b>           |      |                           |            |
|     | Panel Beating                  |      |                           | \$500.00   |
|     | Spray Painting Charge          |      |                           | \$300.00   |
|     | Remove/refix reverse sensor    |      | \$60                      | \$60.00    |
|     | Tuff Kote                      |      |                           | \$60.00    |
|     | Check Lighting                 |      |                           | \$60.00    |
|     | <b>TOTAL LABOUR</b>            |      | 1512.40                   | \$980.00   |
|     | <b>ESTIMATE TOTAL</b>          |      | 4541.100<br>= 2 days<br>* | \$2,650.18 |

4  
 Xnn  
 her  
 Xnn  
 Xnn  
 nee  
 Xnn  
 280  
 250  
 30  
 Xnn  
 Xnn

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9795740  
 'wp' 2/3 resurvey after repair  
 3/1/22 @ Spr  
 2 days tanpin@kha.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer