


BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg No. 201908617D. GST Reg No. 201908617D



FINAL REPORT

Estimate No. : 21998841
Date Estimated : 04/01/2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Mr. Cho Kok Siong

- ACCOUNT -
Budget Direct Insurance
190 Clemenceau Avenue
#03-01
Singapore Shopping Centre
Singapore 239924
Motor Claims Department

REGN. NO.
SMQ7883D

CHASSIS NO.
5P16952

REGN. DATE
2/12/2019

MODEL
216i

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper trim include making good the bumper panel and knocking out dents caused by the accident		720.00
To spray paint the rear bumper		680.00
To check electrical wiring systems and lightings at the rear section include resetting and checking airbags for proper function		200.00
Sundries		80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
B51.12.7.480.322 Bumper trim, rear	1,050.65	1.00	1,050.65

Total Labour :	1,680.00
Total Parts :	1,050.65
Total Labour & Parts :	2,730.65
Deduction for Excess :	
Total Repair Costs less	2,730.65
GST @7%:	191.15
Grand Total :	2,921.80