

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A
#04-07/#04-16 AMK AUTOPOINT
SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump sum
Repair
len 25%

Not Authorized
11/11/2016 @ 6500h
Money After Paying
5 days

SLH 2388J	Mercedes E200	List Price \$	
Paints		mers len 10%	
Bootlid	2110	Bu 2950	✓
Bootlid Mers badge	75	in 135	✓
Bootlid "E200" emblem	82	in 115	✓
Bootlid lock		in 325	✓
Rear Bumper	1080	Bu 1840	✓
Rear Bumper PDC reverse sensor	C \$316 x 4pc	Shory 1264	4pc
Rear Bumper reverse sensor wire harness		in 280	X
Rear Bumper Lower spoiler	603	in 668	✓
Rear Bumper centre brackets @ \$29 x 2pc		in 58	X
Rear Bumper side retainers @ \$71 x 2pc		in 154	X
tail lamps @ \$875 x 2pc		in 1750	X
tail lamp lower bracket @ \$90 x 2pc		in 180	✓
Exhaust chrome end pipe @ \$375 x 2pc		in 750	X
Exhaust chrome end pipe bracket @ \$88 x 2pc		in 176	X
Headrest @ \$980 x 2pc		in 1960	X
Boot weatherstrip		in 220	X
Rear end panel top garnish		in 222	X
Rear Bumper centre trim		in 215	X
Rear Bumper reinforcement beam	765	Bu 865	✓
Rear end panel	1245.00	109 Bu 1330	✓

Special Nett items	Nett Price \$	
Bootlid "C&C" badge	in \$85	✓
Bootlid reverse camera	in \$480	X
Rear end panel top garnish clips	in \$30	X
Exhaust chrome end pipe bracket rivets @ \$20 x 4pc	\$80	X
End panel sealant	in \$80	305m

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
Repair
len 20%.

SLH 2388J

Mercedes E200

Labour charges

Cost \$

- 1) To Renew damaged parts & repair the accident area. 1200 60%
- 2) To Repair & reset headrest. 250 X
- 3) To install reverse camera & check for proper function. 80 50%
- 4) To spray paint bootlid, Rear Bumper & rear end panel 900 66%
- 5) To check with Mer's star diagnose Computer & clear all fault code 250 X
- 6) To carry out anti-rust treatment at the accident area 120 60%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: