

Our Ref : TP/202112/C0011
Accident date: 31/12/2021
Your Ref : SMR9391M

31/12/2021

Motor Claim Department
QBE INSURANCE (SINGAPORE) PTE LTD
1 Wallich St
#35-01 Guoco Tower
Singapore 078881

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SMR9391M
Model : HYUNDAI AVANTE

1pc	Front bumper	/ P.S	\$	474.40	✓
10pcs	Front bumper clips	/ abc	\$	49.00	✓
1pc	Front bumper retainer Rh	/ cut	\$	18.70	✓
1pc	Foglamp Rh	/ cut X NN	\$	164.80	
1pc	Headlamp Rh	/ cut	\$	3,034.00	✓
1pc	Front fender Rh	/ cut buc	\$	1,227.00	✓
1pc	Front right undershield	/ cut	\$	85.70	✓
10pcs	Front right undershield clips	/ abc	\$	49.00	40
1pc	Front right rim	/ cut	\$	1,298.20	450(SN)
1pc	Front right absorber	/ X NN	\$	372.50	
1pc	Front right knuckle	/ X NN	\$	363.60	
1pc	Front right bearing	/ cut DM	\$	452.80	398
1pc	Front right lower arm	/ X NN	\$	296.80	
1pc	Side mirror cover Rh	/ cut CA	\$	40.60	✓
1pc	Side mirror signal Rh	/ cut X NN	\$	95.60	X
1pc	RH side mirror assy	/ cut Abw - photo X NN	\$	642.70	X
1pc	Front right door	/ BT	\$	1,831.10	✓
1pc	Front right door handle	/ cut	\$	179.10	✓
1pc	Front right door chrome mldg	/ X NN	\$	65.10	
1pc	Front door top hinge	/ X	\$	74.20	
1pc	Front door lower hinge	/ X	\$	74.20	
1pc	Front door regulator gear	/ X NN	\$	274.50	
1pc	Front door regulator motor	/ X NN	\$	384.20	
1pc	Front door rubber	/ X NN	\$	138.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
6453 2121 (4 lines) / 6458 1111 (24 hrs)
6459 9795 / 6459 0433
admin@vinsautogroup.com.sg
www.vinsautogroup.com.sg

Our Ref : TP/202112/C0011
Accident date: 31/12/2021
Your Ref : SMR9391M

31/12/2021

1pc	Rear right door	X Repair	\$	1,775.00
1pc	Rear right door handle	X	\$	95.00
1pc	Rear door top hinge	X	\$	74.20
1pc	Rear door lower hinge	X	\$	74.20
1pc	Rear door regulator gear	X NN	\$	274.50
1pc	Rear door regulator motor	X NN	\$	384.20
1pc	Rear door rubber	X	\$	138.70
1pc	Rear right door chrome mldg	X	\$	65.10
				\$ 14,567.40 7377.6
Less 20%				\$ 2,913.48
				\$ 11,653.92 5902.08


To Repair damages
To spray painting
Alignment
Repair and replace front undercarriage
Reset headlamp system

\$	980.00	600.
\$	1,200.00	800 900.
\$	150.00	60.
\$	300.00	X NN
\$	180.00	30.
\$	14,463.92	

VIN'S MOTOR PTE LTD

7942.08

-20%: 6350



6 Days.

After repair photos.

Caroline - 8288282

04/1/22

R000336
31.12.21 14:31
SMR9391M



SMR9391M

EURO CAR DIGITAL ALIGNMENT &
AUDIO ACCESSORIES

Hyundai : Avante/Elantra/Lantra : CN7 (2020-) : without Independent Rear Suspension
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°09'	-0°09'	-0°52' 0°08'
4°24'	4°24'	4°03' 5°03'
-0°09'*	-0°09'*	-0°03' 0°09'
8°16'*	8°16'*	14°00' 15°00'
8°08'*	8°08'*	13°08' 15°08'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°03'*	-2°03'*	-0°52' 0°08'
4°18'	4°18'	4°03' 5°03'
-0°32'*	-0°31'*	-0°03' 0°09'
11°42'*	11°42'*	14°00' 15°00'
9°39'*	9°39'*	13°08' 15°08'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°55'	1°55'	
0°06'	0°06'	
-3°26'	-3°26'	
-0°40'*	-0°40'*	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°17'	-1°17'	-1°42' -0°42'
0°04'	0°04'	-0°01' 0°17'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°19'	-1°19'	-1°42' -0°42'
0°09'	0°09'	-0°01' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°03'	0°03'	
0°13'	0°12'	-0°02' 0°34'
-0°03'	-0°03'	

* This value is not within specification. Tire wear, handling and safety problems may result.