

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP ALG.
Xiao Chen.

ESTIMATE

Name : SALEHUDDIN B RAMADHAN
Vehicle No : SGZ 6595 R

Make/Model : MITSUBISHI LANCER
Accident date : 27.12.2021

JMYSTCS3A8U0030

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bumper <i>rehd</i>	1	\$ 821.70 <i>696</i>
2	Rear bumper side holder @ \$44.00 <i>RH New</i>	2	\$ 88.00 <i>44</i>
3	Rear bumper lower lip <i>onehd</i>	1	\$ 480.00 <i>✓</i>
4	Rear RH lamp <i>at</i>	1	\$ 344.30 <i>✓</i>
5	Rear RH fender <i>RHS</i>	1	\$ 690.80 <i>+</i>
6	Rear end panel <i>new</i>	1	\$ 465.30 <i>+</i>
			\$ 2,890.10
		Less 10% Disc	\$ 578.02
		Total	\$ 2,312.08

Special Nett Items

1	Rear bumper clips (1 set) <i>New</i>	1	\$ 60.00 <i>30</i>
2	Rear bumper reverse sensor (1 set) <i>new</i>	1	\$ 380.00 <i>+</i>
		Total	\$ 440.00

Labour Cost

1	Remove & reinstall reverse sensor	\$ 200.00 <i>50</i>
2	Remove & reinstall bootlid inner garnish	\$ 200.00 <i>+</i>
3	Remove ,replace & repair consistent to the accident	\$ 1,000.00 <i>300</i>
4	Respray painting	\$ 1,000.00 <i>600</i>
	Total	\$ 2,400.00

Grand Total **\$ 5,152.08** *5441.09*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Total: 2387.87

L/S: 1.9K

03 Days

1.9K