

*ccika*

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_ After-Paint: \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SMR 7063 Z**  
 Model : Honda Vezel  
 Year : 2020  
 Chassis No : \_\_\_\_\_

*DOA ?*

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,840.00	\$ <del>1,840.00</del> 953.00
2	Tailgate logo	1	\$ 95.00	\$ <del>95.00</del> 45.00
3	Tailgate emblem 'VEZEL'	1	\$ 89.30	\$ <del>89.30</del> 66.80
4	Tailgate emblem 'HYBRID'	1	\$ 88.00	\$ <del>88.00</del> 66.30
5	Tailgate outer garnish	1	\$ 455.00	\$ <del>455.00</del>
6	Tailgate lamp	2	\$ 790.00	\$ <del>1,580.00</del>
7	Tailgate inner lock	1	\$ 248.60	\$ <del>248.60</del> 180.20
8	Tailgate inner lock sticker	1	\$ 81.00	\$ <del>81.00</del>
9	Tailgate inner trim board	1	\$ 498.20	\$ <del>498.20</del> 295.00
10	Tailgate handle pocket garnish	1	\$ 98.00	\$ <del>98.00</del>
11	Tailgate windscreen moulding side	2	\$ <del>50.00</del> 118.00	\$ <del>100.00</del> 236.00
12	Tailgate windscreen moulding top	1	\$ 145.00	\$ <del>145.00</del> 100.00
13	Tailgate windscreen moulding bottom	1	\$ 145.00	\$ <del>145.00</del> 100.00
14	Tailgate weatherstrip	1	\$ 185.00	\$ <del>185.00</del> 162.30
15	Tailgate antenna sensor	1	\$ 245.60	\$ <del>245.60</del>
16	Tailgate buzzer	1	\$ 185.00	\$ <del>185.00</del> 107.10
17	Rear bumper	1	\$ 1,185.00	\$ <del>1,185.00</del> 762.70
18	Rear bumper side retainer	2	\$ <del>27.50</del> 88.00	\$ <del>55.00</del> 176.00
19	Rear bumper side garnish	<i>LH 1</i> 2	\$ <del>195.00</del> 245.80	\$ <del>391.60</del> 195.00
20	Rear bumper bracket	2	\$ 136.00	\$ <del>272.00</del>
21	Rear bumper reflector	2	\$ 187.00	\$ <del>374.00</del>
22	Rear bumper lower splash guard	1	\$ 150.30	\$ <del>150.30</del>
23	Rear end panel	1	\$ 985.00	\$ <del>985.00</del> 517.00
24	Rear end panel top garnish	1	\$ 184.00	\$ <del>184.00</del> 122.60
25	Spare tyre panel	1	\$ 782.60	\$ <del>782.60</del>
26	Spare tyre panel top board	1	\$ 486.00	\$ <del>486.00</del>
27	Rear fender inner trim board	2	\$ 980.00	\$ <del>1,960.00</del>
28	Taillamp	2	\$ 889.00	\$ <del>1,778.00</del>
29	Exhaust pipe	1	\$ 895.00	\$ <del>895.00</del>
30	Exhaust mounting	2	\$ 42.50	\$ <del>85.00</del>
31	Exhaust heat sheild	1	\$ 185.00	\$ <del>185.00</del>

*DD ✓*  
*NECV*  
*NDX*  
*NDX*  
*JMV*  
*NDX*  
*BRV*  
*NDX*  
*NECV*  
*TNV*  
*NDX*  
*BRV*  
*BRV*  
*NECV*  
*BRV*  
*NSX*  
*NDX*  
*NDX*  
*DDV*  
*BRV*  
*NDX*  
*NDX*

Parts Sub Total : \$ 3,328.00 16,204.20  
 20% Discount : \$ 765.60 3,240.84  
**PARTS TOTAL : \$ 12,963.36**

*3062.40*

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ <del>80.00</del>
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 20.00 50.00
4	Tailgate lamp clips	2	\$ 50.00	\$ <del>100.00</del>
5	Tailgate lamp seal	2	\$ 60.00	\$ 120.00
6	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00
7	Tailgate windscreen sealant	1	\$ 100.00	\$ 110.00 100.00
8	Tailgate windscreen inner seal	1	\$ 60.00	\$ <del>60.00</del>
9	Tailgate windscreen clips	1	\$ 50.00	\$ <del>50.00</del>
10	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00
11	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
12	Rear bumper side garnish clips	2	\$ 50.00	\$ 20.00 100.00
13	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00
14	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00
15	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
16	Spare tyre panel sealant	1	\$ 100.00	\$ <del>100.00</del>
17	Rear fender inner trim board clips	2	\$ 50.00	\$ <del>100.00</del>
18	Rear fender arch garnish clips	2	\$ 50.00	\$ 100.00
19	Taillamp seal	2	\$ 60.00	\$ <del>120.00</del>
20	Taillamp clips	2	\$ 50.00	\$ <del>100.00</del>
21	Reverse camera	1	\$ 480.00	\$ <del>480.00</del>
22	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 400.00 2,670.00

NNT  
 NECV  
 NNT  
 NECV  
 NSX  
 NNT  
 NECV  
 SCV  
 NECV  
 NNT  
 NNT  
 NNT

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R rear bumper reverse sensor	\$ 60.00 100.00
4	R&R reverse camera	\$ <del>100.00</del>
5	R&R exhaust pipe	\$ <del>150.00</del>
6	Upholstery	\$ 300.00
7	Check wiring	\$ 200.00
8	Diagnostic reset fault code	\$ 300.00
9	Panel beating	\$ 1000.00 1,800.00
10	Rust proofing	\$ 200.00
11	Spray painting	\$ 600.00 1,800.00
LABOUR TOTAL :		\$ 5,350.00

-  
 -  
 -  
 NNT  
 NNT  
 NNT  
 NNT  
 -  
 -

4/1/2022 5/1/2022 Lump sum repair  
 1430 1300hrs Repair days 7  
 Taimin Min Taimin Min

1320.00  
 PARTS TOTAL : \$ 12,963.36  
 SPECIAL NETT TOTAL : \$ 2,670.00  
 LABOUR TOTAL : \$ 5,350.00  
 GRAND TOTAL : \$ 20,983.36

**LKK Auto Consultants** hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

LS 3800/2  
 Taimin Min  
 24/1/2022

Parts 3062.40  
 SN 400.00  
 Labour 1320.00  
 4,782.40  
 @20% 956.48  
 3825.92