

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
Tel: 6747 6106 (6 Lines) Fax: 6744 2368
Email: service@smemotor.com.sg Website: www.smemotor.com.sg
Co. & GST Reg. No: 201119451E

not Authorised
LKK
Wen Y
4/1/22

L/S

Take photo. After repair.
Tel: 62563561
8 days

TP INSURER: India International Insurance Pte Ltd (HQ)
NIL

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	22/III/TP-001(01)
Policy No:		Date of Loss:	31/12/2021
Vehicle Reg. No.:	SKX5485U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YAP LI YUN		
Make/Model:	SUZUKI SX4, 1.6 (A)	Vehicle Reg. Date:	18/12/2015
Vehicle Colour:	RED	Chassis No:	TSMJYB22S00218465
Engine No:	M16A1921764		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS		Amount
Parts		13,829.20
Miscellaneous Items		486.00
Labour		3,420.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		17,735.20
+ GST 7.00% (S\$)		1,241.46
Nett Amount (S\$)		18,976.66

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2022)

Parts: 144 SUZUKI SX4 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX5485U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE	0.00	0.00	22 *600.00 F
2	1		*REAR GATE SUZUKI PLATE	0.00	0.00	111 *25.00 F
3	1		*REAR GATE S-CROSS SX4 PLATE	0.00	0.00	111 *27.00 F
4	1		*REAR GATE LOCK	0.00	0.00	111 *195.00 F
5	1		*REAR GATE INNER RUBBER	0.00	0.00	111 *125.00 F
6	1		*REAR BUMPER (TOP)	0.00	0.00	111 *330.00 F
7	1		*REAR BUMPER (LOWER)	0.00	0.00	111 *360.00 F
8	2		*REAR BUMPER RETAINER	0.00	0.00	111 *40.00 F
9	10		*REAR BUMPER CLIPS	0.00	0.00	111 *30.00 F
10	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	111 *195.00 F
11	1		*REAR END PANEL	0.00	0.00	111 *290.00 F
12	1		*REAR END PANEL TOP GARNISH	0.00	0.00	111 *95.00 F
13	6		*TOP GARNISH CLIPS	0.00	0.00	111 *18.00 F
14	1		*FRT BONNET	0.00	0.00	111 *550.00 F
15	1		*FRT BONNET INSULATOR	0.00	0.00	111 *150.00 F
16	8		*INSULATOR CLIPS	0.00	0.00	111 *24.00 F
17	1		*FRT BONNET LOCK	0.00	0.00	111 *45.00 F
18	1		*FRT GRILLE	0.00	0.00	111 *195.00 F
19	1		*GRILLE CENTRE LOGO	0.00	0.00	111 *25.00 F
20	1		*GRILLE OUTER MOULDING (NO STOCK)	0.00	0.00	111 *195.00 F
21	4		*GRILLE CLIPS	0.00	0.00	111 *12.00 F
22	1		*FRT BUMPER (TOP) AGENT	0.00	0.00	111 *420.00 F
23	2		*FRT BUMPER RETAINER	0.00	0.00	111 *36.00 F
24	10		*FRT BUMPER CLIPS	0.00	0.00	111 *30.00 F
25	1		*FRT BUMPER (LOWER) AGENT	0.00	0.00	111 *360.00 F
26	1		*FRT BUMPER LOWER SPOILER	0.00	0.00	111 *125.00 F
27	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	111 *265.00 F
28	2		*HEADLAMP	0.00	0.00	111 *5,500.00 F
29	1		*HEADLAMP SUPPORT PANEL ASSY	0.00	0.00	111 *550.00 F
30	1		*AIRCON CONDENSER (NO STOCK)	0.00	0.00	111 *800.00 F
31	1		*RADIATOR	0.00	0.00	111 *530.00 F
32	1		*RADIATOR MOTOR ASSY	0.00	0.00	111 *430.00 F

F=Franchise part.

Sub Total (\$\$) 12,572.00
+ Margin on L,N Items 10.00% (\$\$) 1,257.20
Total Parts (\$\$) 13,829.20

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRT NUMBER PLATE		
2	1	RADIATOR COOLANT	Best	40.00 ✓
3	1	REAR WINDSCREEN GUM	yes	25.00 ✓
4	1	REVERSE SENSOR (4 PCS)	yes	60.00 ✓
5	1	OD/TP Case (Insurer)	Shah	350.00 20
			see	11.00 ✓
Sub Total (\$\$)				486.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	WIRE CHECKING		
2	REMOVE & REFIX REAR WINDSCREEN	New	30.00 ✓
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00 ✓
4	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	150.00 80
5	REMOVE & REFIX AIRCON AND GAS	New	120.00 90
6	LABOUR CHARGE	New	100.00 ✓
7	SPRAY PAINTING	New	1,500.00 1100
		New	1,400.00 1200
Gross Labour Cost (\$\$)			3,420.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >