

Toyotsu Binter Automotives Parts Pte Ltd

File No : SH/2021
Date : 04-February-2022



Estimated cost of repair for vehicle no : SJA 3869 S Model Honda Fit
Accident involving vehicle no: SJA 3869 S & GBG 1658 K on 02.01.2022

Description	Quantity	Cost Price
RH head lamp <i>Bo ✓</i>		
Front bumper <i>Bo ✓</i>		
RH Front bumper retainer <i>Bo ✓</i>		
RH front fender <i>Bo ✓</i>		
RH front door side mirror base <i>CPA</i>		
RH front door side mirror cover <i>Bo</i>		
RH front door side mirror glass <i>?</i>		
RH front wheel rim 15" <i>Bo ✓</i>		
RH front knuckle arm <i>?</i>		
RH front knuckle arm wheel bearing <i>?</i>		
RH front lower arm <i>?</i>		
RH front shock absorber <i>?</i>		
RH front shock absorber top mounting <i>?</i>		
Steering rack and pinion <i>?</i>		
RH steering tie rod <i>?</i>		
RH steering tie rod end <i>?</i>		
RH drive shaft <i>R X</i>		
RH front stabilizer bar link <i>Bo X</i>		
To computer wheel alignment	\$	60.00 ✓
To spray back original underseal, tuff-kote	\$	600.00 301
Remve and fix front right wheel undercarriage	\$	260.00 ?
To spray painting front right damaged portion	\$	580.00 504
Labour charge	\$	650.00 4801

T/Party: AI G

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*NOT Withheld
11/2/22
Survey After Paint*