

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2201/001
Policy No:	5109306706-02	Date of Loss:	31/12/2021
Vehicle Reg. No.:	SJR319T	Driveable?	yes
Driver Age:	13/06/1965	Third Party Vehicle No.:	SLE6619H
Any Injuries?	no	Contact No:	98766994
Insured/Claimant:	NI TECK MING	Driver:	NI TECK MING

PARTS MODEL

Make/Model:	Toyota, Vios - MR053HY420	Vehicle Reg. Date:	
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	2,517.92
Miscellaneous Items	475.00
Labour	800.00
Paintwork Labour	650.00
Towing	0.00
Gross Total(S\$):	4,442.92
GST 7.00%(S\$):	311.00
Nett Amount(S\$):	4,753.92

This claim is handled by: Tee Shu yi

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER / CAT	422.02	-10.00	379.82
2	1	FRONT BUMPER LOWER SPOILER X Repair	337.50	-10.00	303.75
3	1	FRONT BUMPER SIDE RETAINER RH / Sale	68.30	-10.00	61.47
4	1	FRONT BUMPER SIDE RETAINER LH / Sale	68.30	-10.00	61.47
5	1	FRONT BUMPER FOG LAMP RH X Repair	287.90	-10.00	259.11
6	1	FRONT BUMPER FOG LAMP COVER RH X Repair	86.57	-10.00	77.91
7	1	FRONT HEADLAMP RH / CAT	397.60	-10.00	357.84
8	1	FRONT FENDER RH / BNC	551.30	-10.00	496.17
9	1	FRONT FENDER INNER SHIELD RH / BNC	95.60	-10.00	86.04
10	1	FRONT DOOR RH X Repair	482.60	-10.00	434.34
Total Parts (\$)					2,517.92

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS / BNC	40.00	0.00	40.00
2	1	FRONT NUMBER PLATE X Repair	45.00	0.00	45.00
3	1	FRONT FENDER INNER SHIELD CLIPS / BNC	40.00	0.00	40.00
4	1	WHEEL RIM / CAT	350.00	0.00	350.00
Sub Total (\$)					475.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00
Gross Labour Cost (\$)					800.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	650.00	0.00	650.00
Gross Labour Cost (\$)					650.00

4 Days -
 Lump sum Repair
 After repair photos
 Gino Q. P
 05/1/22

< END OF ESTIMATES >