

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000111/TVY3E2

Date: 01/04/2022

REFERENCE

Insured/Claimant: AKKIHEBBAL LAKSHMINARAYANA SATYA PRAKASH Policy No: 2070116674-01

Date of Loss: 28/12/2021

Nature of Claim: OD

Claim No: 4689837475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU5348A	Engine No:	CHZC34240
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V3LA000409
Reg. Date:	17/08/2020 (Man. Year: 2019)	Odometer:	17668 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,646.00	1,744.80	1,901.20	52.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	1,522.00	3,850.00	71.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,018.00	3,266.80	5,751.20	63.77
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,718.00	2,966.80	5,751.20	65.97
+ GST 7.00/7.00% (S\$)	610.26	207.68	402.58	65.97
Nett Amount (S\$)	9,328.26	3,174.48	6,153.78	65.97

INSPECTION

Date of Assignment: 04/01/2022

Date Inspected: 04/01/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	1		*REAR BUMPER ADAPTER - RH	Not Necessary	38.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	32.00 FS	*- FS
5	2		*REAR BUMPER LOCKING MECHANISN - LH / RH	Not Necessary	59.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Cut	237.00 FS	*189.60 FS
7	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	41.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 FS	*- FS
9	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	56.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION OUTER - RH	Not Necessary	66.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
13	1		*REAR FENDER VENT TRIM - RH	Not Necessary	68.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 3,646.00 1,744.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY REAR BUMPER, REAR END PANELLING AND RHS REAR FENDER	New	2,800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,372.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >