

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM22000113/Urs3q2
	8 SHENTON WAY AXA TOWERSING			Date:	19/01/2022
	ATTN:CYNTHIA			Code:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 3255L	Veh. Inspected	l	SLP 777R
	Policy No.	P2419138	Coverage (\$)		0.00
	Claim No.	S2M03Q03	Excess (\$)		0.00
	Assign From		Assign Date		04/01/2022
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. X4 (A)	c.c		1997
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	WBAXW120700G74386	Colour		BLACK
	Odometer	115277 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/50 R18	HANKOOK		6 mm
	L/H Front Tyre	245/50 R18	HANKOOK		6 mm
	R/H Rear Tyre	245/50 R18	HANKOOK		6 mm
	L/H Rear Tyre	245/50 R18	HANKOOK		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/12/2021	Inspection Dat	е	04/01/2022
	Survey held at	JEMENTAH MOTOR WORKS			
		BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				