

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : SMP 5972Z

Make: Honda Vezel

Date: 14/01/2021

Spare parts

QTY	List Price	Price	(S\$)
1	Tailgate	953	1172.10
1	Rear Bumper lower cover		115.20
1	Rear Bumper Reflector LH		121.30
1	Rear Bumper	549.20	553.10
1	Rear Bumper Side LH		155.50
1	Rear Bumper Side Retainer LH		60.80
1	Bumper Sensor		97.50
1	Rear End Panel		470.20
1	Rear End Panel Top Garnish		123.60

Spare Parts Subtotal

2869.30

Special Nett Items

Qty		
1	Rear bumper clip	45
2	Rear reverse sensor	250

Rear Number plate (OPC car) 40 net ✓

295

Labour charges

S/N		(S\$)
1	To tuff coat affected areas	100
2	To remove and refix rear windscreen glass	120
3	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	1200
4	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	1200
5	To remove and refit. Wiring for front sensor	120

Labour charges: Subtotal

2740

⑥ To Reseal Rear No. plate from LTA

60 net ✓

ESTIMATES PARTS AND LABOR GRAND TOTAL:

5904.30

1517.60

270

1640

3427.60

4152700

05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfah 97495749

'WP' 10/1/22 @ 2pm

1/5 Resurvey after repair

5 days

Tanfah e handover.