ESTIMATE

: ACCIDENT/BODY REPAIRS

WORKSHOP

: LENG KEE

CONTACT NO

: 67038511

REFERENCE

: 002/IC/TCAC/SAY/2022

DATE

: 04-JAN-2022

LONPAC INSURANCE BHD (INCORPORATED IN MALAYSIA)

100 BEACH ROAD #19-00

SHAW TOWER S(189702)

TEL: 62507388

FAX: 62962706/62963767 ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MDM KHO MAY LING DIANA

ADDRESS

: BLK 121D SENGKANG EAST WAY

#13-77

S(544121)

TELEPHONE NO

: 93854273

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO

: 2100500438-04

VEHICLE NO

: SLL1197D

MODEL CODE

: FRLARBZJ11UEA--A--

MODEL/YEAR

: NISSAN QASHQAI 1.2

ENGINE NO

: HRA2351512A

CHASSIS NO

MILEAGE

: SJNFEAJ11U1817494

DATE IN

: 86725 KM : 04/01/2022

LIABILITY :

0.00

EXCESS CLAUSE :

0.00

ESTIMATE BY : SAYEDINAH

ACCIDENT DATE : 31/12/2021

A 1 PL/4 | 111/1/12/17

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL1197D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	CONDUCT 3RD PARTY CLAIM LONPAC DATE:31/12/21 TIME:1050 LOCATION:SENG POH ROAD	a <b>3</b> 90	-04
2 ZZ/002	REPAIR/REPLACE REAR BUMPER, END PANEL&RH RR FENDER,	1170.00	
3 ZZ/003	RESPRAY REAR BUMPER, ENDPANEL & REAR RH FENDER	750.00	500
4 ZZ/004	CHECK ALL LIGHTING AFTER REPAIR	48.00	
5 ZZ/005	QC & CONSULT CHECK		
6 ZZ/006	CARWASH & VACUUM		
			-
	TOTAL LABOUR CHARGES	1968.0	0

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL1197D

		DAMAGED F	DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS	
1 FENDER OVER FENDER	93828-4EA0A	540.50			
2 BRACKET-BUMPER RH 7	85220-4EA0A	38.90			
3 FASCIA-RR BUMP CAL	85022-4EAOH	876.40			
4 LAMP COMB RR,RH	26550-4EA0A	346.90			
SUB TOTAL LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/	/NETT00%)	1802.70 360.54	0.00	0.00	
GRAND TOTAL		1442.16	0.00	0.00	
OVERALL TOTAL		1442.16			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

## SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL1197D

TOTAL LABOUR CHARGES

1968.00

TOTAL SPARE PARTS CHARGES

1442.16

**GRAND TOTAL** 

3410.16 \*

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY REMARKS

R984-Hp 90010068 : 06/01/22 @1048 : 0.00 Y days Read be four peint

PLS NOTE: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: