

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5828K*Not Notified**11 Rmp 83250/1* AAD2112-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

03 JAN 2015

SHC5828K

VF1ABL15AUC282179

RENAULT

LATITUDE

30/12/2021

China -

03/08/2015

PART		LIST
1 BUMPER COVER REAR	\$	<i>R</i> 561.70 ✓
1 BUMPER LOWER REAR	\$	<i>R</i> 411.90 X
1 BUMPER REFLECTOR LH	\$	<i>R</i> 16.60 X
1 BUMPER REFLECTOR RH	\$	<i>R</i> 16.60 X
1 BUMPER BRACKET CTR REAR	\$	<i>R</i> 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$	<i>R</i> 82.10 X
1 BUMPER RETAINER RH REAR	\$	<i>R</i> 59.80 ✓
1 BUMPER BRACKET SIDE LH REAR	\$	<i>R</i> 80.80 X
1 BUMPER RETAINER LH REAR	\$	<i>R</i> 54.20 X
1 FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20 ✓
1 WHEELARCH REAR RH	\$	<i>R</i> 275.40 X
1 ABSORBER REAR	\$	<i>R</i> 217.30 X
1 BUMPER BEAM REAR	\$	<i>R</i> 547.80 X
1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50 X
1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80 X
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>R</i> 404.56 X
1 BOOT REFLECTOR LAMP RH	\$	<i>R</i> 277.70 X
1 TAILLAMP RH	\$	<i>R</i> 401.40 ✓
	\$	15,947.26
10%	\$	1,594.73
	\$	14,352.53

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

\$

R 700.00 X

\$

R 66.00 ✓

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5828K

1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	X
1 EXHAUST MOUNTING REAR	\$	sm	17.82	X
2 WINDSCREEN SEALANT	\$	na	150.00	40sm
1 WINDSCREEN MOULDING	\$	na	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	30sm
TOTAL	\$		1,509.82	
TOTAL PARTS	\$		15,862.35	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120/
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	440/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600/
To Rust-Proofing Of The Affected Areas.	\$	170.00	30/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5828K

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *in* 170.00 *X*

To check steering geometry and computer wheel
alignment \$ *in* 220.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,880.00

Over All Total \$ 38,094.89

(LUMP SUM)

Repair Days *20 DAYS*
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: