

Not Notified

11 Rmp \$3250/- AAD2112-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5828K

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

03 JAN 2021

SHC5828K

VF1ABL15AUC282179

RENAULT

LATITUDE

30/12/2021

China -

03/08/2015

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH
- 1 ABSORBER REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel)TRIM
- 1 BOOT REFLECTOR LAMP RH
- 1 TAILLAMP RH

LIST

\$	Bu	561.70	✓
\$	Sn	411.90	X
\$	Sn	16.60	X
\$	Sn	16.60	X
\$	Sn	98.10	X
\$	Sn	82.10	X
\$	Sn	59.80	✓
\$	Sn	80.80	X
\$	Sn	54.20	X
\$	Bu	1,933.20	✓
\$	Sn	275.40	X
\$	Sn	217.30	X
\$	Sn	547.80	X
\$	Sn	114.50	X
\$	Sn	114.50	X
\$	Sn	745.80	X
\$	Sn	404.56	X
\$	Sn	277.70	X
\$	Bu	401.40	✓

\$ 15,947.26

10% \$ 1,594.73

\$ 14,352.53

Special Net

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP

\$	Sn	700.00	X
\$	Sn	66.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-**SHC5828K**

1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	X
1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
2 WINDSCREEN SEALANT	\$	nn	150.00	405ml
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	301ml
TOTAL	\$		1,509.82	
TOTAL PARTS	\$		15,862.35	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120l
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	440l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600l
To Rust-Proofing Of The Affected Areas.	\$	170.00	30l
To reinstall rear bumper parking sensor.	\$	170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To repair and realign rear exhaust pipe.	\$	h	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	h	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	h	170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHC5828K

To transfer of rear windscreen fittings and conduct
water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,880.00

Over All Total \$ 38,094.89

(LUMP SUM)

Repair Days

20 DAYS

4 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: