



Case Details

Case Reference Number :
TAX/12/21/2068
Type of Repair : Accident Repair
Vehicle Registration Number :
SHB5377A

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17119-ID
Assigned By : Tan Lee Ge #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Vehicle Age (in Months)
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓ X NN
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	✓
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	✓ X NN
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	✓ X NN

Total Spare Part Cost 5,457.23

Lump Sum Discount (%) 20.00

Final Spare Part Cost 4,348.50

Surveyor Total 940.10

Lump Sum Dis (%) 20

Final Sur Total 752.08

SMRT Recommendation										Surveyor Approval				
Item Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50 ✓	15.00	25.00	11.25	Replace	10	11.25	Replace ✓	MOC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	✓	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace ✓	Aut
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	✓	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace ✓	MOC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give ✓	X / NN
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give ✓	X / NN
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check ✓	X NN
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give ✓	X
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give ✓	X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give ✓	X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give ✓	X
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give ✓	X
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give ✓	X
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give ✓	X
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give ✓	X
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair ✓	X Repair

Total Spare Part Cost 5,457.23

Surveyor Total 940.10

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,348.50

Final Sur Total 752.08

022, 10:33

https://vacswest.smt.com.sg/estimation.aspx

SMRT Recommendation												Surveyor Approval		
JOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	✓	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace ✓	✓
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1✓	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace ✓	✓
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1✓	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace ✓	✓
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Not Give ✓	X ✓
One Time Key In	Main			STRIDES LOGO	1✓	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ✓	✓
One Time Key In	Main			STICKER DECAL 6555 8888	1✓	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ✓	✓
Total Spare Part Cost									5,457.23	Surveyor Total		940.10		✓
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,348.50	Final Sur Total		752.08		✓

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	250	✓
Total:			507.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	X ml
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	✓
4	Main	TO RESPRAY REAR SPOILER	180.00	0	X ml
Total:			918.00	300.00	

Other Cost Detail

04/01/2022, 15:55

https://vacsweb.smrt.com.sg/estimation.aspx

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	✓
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	} un
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	✓ NEC
Total:			656.88	336.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,348.50	752.08
Total Labour Cost	507.00	250.00
Total Spray Painting	918.00	300.00
Other	656.88	336.88
Overall Total	6,430.38	1,638.96
Lump Sum Repair Option	☐	☒
Lump Sum Total	6,450.00	1,650.00 ✓
Surveyor Approved Amount		1,650.00
No of Repair Days*	5	3 ✓
Remarks	-	LUMP SUM REPAIR / AFTER PAINT PHOTO
Surveyor Name		GuoQiang
Signature		
		Save Clear
Survey Date	04/01/2022	