

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

🖨

📄

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO22000124/Atf3	
50 RAFFLES PLACE #03-03			Date: 05/01/2022	
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDW 8178A	Veh. Inspected	SKB 4853M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200011/THE(nr)	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	05/01/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/12/2021	Inspection Date	05/01/2022	
Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				