

T & S MOTOR SERVICE
 Blk 5035 Ang Mo Kio Industrial Park 2
 #01-357 Singapore 569538
 Tel: 64845518 Fax: 64815828

Date : 10/01/2022

NTUC Income Insurance Cooperative Limited
 75 Bras Basah Road
 NTUC Income Centre
 Singapore 189557

Re: Estimated repair cost of Toyota Prius Hybrid SMD4036X accident on 31/12/21
 involved with SLD1826P.

1 pc	Rear bumper	✓ <i>re</i>	\$ 485.60
1 pc	Rear bumper lower spoiler	✓ <i>cut</i>	\$ 326.40
1 pc	Rear bumper LH lamp	✓ <i>X</i>	\$ 286.20
2 pcs	Rear bumper side retainer	@ \$ 78.00 <i>X</i>	\$ 156.00
1 pc	Rear bumper inner reinforcement	✓ <i>47</i>	\$ 519.30
1 set	Front bumper clip	✓ <i>162</i>	\$ 40.00
1 set	Reverse sensor	✓ <i>AN</i>	\$ 250.00
			<u>\$ 2,063.50</u>

Labour charge for remove ,panel beat ,ealding ,align and renew replaced parts. \$ 700.00 *200*

Spray painting on rear bumper and accident affected areas. \$ 600.00 *200*

To check wiring and lightings. \$ 50.00 *X*

To conduct wheel alignment. \$ 60.00 *X*

TOTAL:

\$ 3,473.50

2 Days
coupon repair
After up in photos
Gino Awf
10/1/22

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: