

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0924/2021/JT
DATE : 12-Nov-21
WIP : 53283

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 16/11/21

YOUR INSURED VEH NO : GBL 5822 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

6 days - ok - Jy - 14 Apr 22

OWNER'S NAME : MR DENNIS BELING
ADDRESS : 27 OXLEY WALK
#03-26
SINGAPORE 238596
TELEPHONE : HP +65 88895474
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070126304
VEHICLE NO : **SMU 7868 C**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 28/08/2020
ENGINE NO : CZD 897587
CHASSIS NO : WAUZZZF3XL1116157
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 09-Nov-21
PLACE OF ACCIDENT : ALONG FORT CANNING ROAD AFTER
TRAFFIC LIGHT JUNCTION OF BENCOOLAN
ST AND STAMFORD ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 7868 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER MODULE DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,250.00
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR.	\$	3,000.00	\$	1,650.00
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 7,032.00	\$	4,012.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7868 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,634.00	
2	REAR BUMPER FIXING PARTS	1	\$ 211.00	
3	REAR BUMPER SPOILER	1	\$ 459.00	\$ 367.20
4	REAR LIGHT REFLECTOR - RH	1	\$ 41.00	
5	LED TAIL LIGHT - RH	1	\$ 926.00	
6	REAR BUMPER GUIDE SECTION - RH	1	\$ 63.00	
7	REAR WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$ 428.80
8	REAR DOOR - RH	1	\$ 2,909.00	\$ 2,327.20
9	REAR OUTER DOOR SEAL - RH	1	\$ 135.00	\$ 108.00
10	REAR DOOR CATCH - RH	1	\$ 120.00	
11	REAR DOOR HANDLE, EXTERIOR - RH	1	\$ 198.00	
12	REAR DOOR HANDLE CAP - RH	1	\$ 27.00	
13	REAR DOOR DOOR COVER - RH	1	\$ 257.00	\$ 205.20
14	REAR ALUMINIUM RIM - RH	1	\$ 1,262.00	\$ 1,009.60
15	REAR WHEEL HOUSING LINER - RH	1	\$ 241.00	
16	REAR UNDERBODY TRIM - RH	1	\$ 52.00	
17	METAL FILLER POWDER	S/N	\$ 280.00	
18	STONE CHIP	S/N	\$ 180.00	
19	SUNDIRES	1	\$ 300.00	\$ 7.28
TOTAL SPARE PARTS			\$ 9,831.00	\$ 4,453.28
TOTAL LABOUR CHARGES			\$ 7,032.00	\$ 4,012.00
GRAND TOTAL			\$ 16,863.00	\$ 8,465.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT