



**TRANS EUROKARS PTE LTD**  
27A TANJONG PENJURU, SINGAPORE 609042  
**FINALIZE COST OF REPAIRS**



<b>INDIA INTERNATIONAL INSURANCE P/L</b> 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> <b>ADDRESS :</b>  <b>TEL :</b>		<b>WIP :</b> 44986 <b>EXCESS :</b> <b>DATE:</b> 5-Jan-22	
<b>VEH NO :</b>	<b>SMW6973C</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	JESS
<b>CHASSIS NO :</b>	JM6GL1073L0405846	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MAZDA 6	<b>DATE REG.</b>	1-Dec-20	<b>POLICY NO. :</b>	

<b>NATURE OF WORKS</b>									
NO	DESCRIPTION	QTY	UNIT PRICE	DISC %	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1	1,154.80	-	✓		MGSK2-50-221ABB	1,154.80	1,154.80
2	TAPE,PROTECTOR	4	4.70	-	✓		MBCKA-50-EM1	18.80	18.80
3	RETAINER S.S ULTRASONIC CENTER	2	18.20	-			MKD45-67-UC5A13		36.40
4	SENSOR ULTRASONIC CENTER	2	181.70	-			MGMK6-67-UC1 13		363.40
5	BRACKET CENTER REAR BUMPER	1	5.40	-			MDFR5-50-251		5.40
6	REINFORCEMENT REAR	1	538.30	-			MGHK1-50-260		538.30
7	TAPE SEAL	2	13.70	-	✓		MGSH7-50-2G1	27.40	27.40
8	COVER TOWING RH REAR	1	46.60	-	✓		MGSH7-50-EK1 BB	46.60	46.60
9	REFLECTOR RH	1	41.20	-			MGRF5-51-5L0A		41.20
10	RIVET	2	9.20	-	✓		MTK21-50-355	18.40	18.40
11	FASTENER	6	8.00	-	✓		MEA01-50-037	48.00	48.00
12	GASKET TAIL LAMP RH	1	46.00	-	✓		MGRF5-51-153	46.00	46.00
13	GASKET TAIL LAMP LH	1	46.00	-	✓		MGRF5-51-163	46.00	46.00
<b>SUPPLEMENTARY</b>									
NO	DESCRIPTION	QTY	UNIT PRICE	DISC %	1st	Supp	PARTS NO	REVISED	PRICES
1									
<b>TOTAL PARTS</b>								1,406.00	2,390.70
								-	
<b>TOTAL PARTS COST</b>								<b>1,406.00</b>	<b>2,390.70</b>
<b>Labour Description</b>									
								REVISED	PRICES
1		REPLACE REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT. 169391						660.00	1,320.00
2		SPRAY REAR BLMER.						630.00	1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.						330.00	660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.						180.00	250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.						250.00	300.00

6	MZ-BR-SUNDRI	SUNDRIES.	20.00	50.00
---	--------------	-----------	-------	-------

**SUPPLEMENTARY LABOUR DESCRIPTION**

1	SUNDRIES	APPLY CERAMIC COATING ON THE AFFECTED AREA. REAR BUMPER.	90.00	
---	----------	--	-------	--

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	2,160.00	3,840.00
TOTAL PARTS	1,406.00	2,390.70
TOTAL	<b>3,566.00</b>	<b>6,230.70</b>
LESS EXCESS	-	-
TOTAL AFTER EXCESS	3,566.00	
GST 7%	249.62	-
<b>GRAND TOTAL</b>	<b>3,815.62</b>	-
<b>REPAIR DAYS</b>	<b>3.00</b>	

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
Authorised Signature