

ASS. REC. BY:

REF:

AG/ 22000131/Ke

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ Ab Lim

of \_\_\_\_\_

Insured: \_\_\_\_\_ 0221

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_


(Client's Record)

Make of Veh: \_\_\_\_\_

10-30cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SC7 262m Yr Regn: 07, 17

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Veel c.c. 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 66889 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RUI 1220826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 3/1/22 D.O.I. 6/1/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1  
23/2 L1 Rpt @ 1950h Car

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation: \_\_\_\_\_  
S + RS. SI

Fuel/As

Others

TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : PANG ENG POH  
 35 LOR ONG LYE  
 #05-07  
 SINGAPORE 536443

Estimate No: MC1902391  
 Date: 05 Jan 2022  
 Policy No: GA238524/1  
 Veh Reg No: SCZ262M  
 Make/Model: HONDA VEZEL 1.5X

*Ucic  
1030*

ATTN:  
 Your Ref No: SCZ262M  
 Claim Type: Third Party → *AMK*  
 Accident Date: 03/01/2021  
 TP Veh Reg No: SKT4709C

*NOT Authorized  
 11 Sep @ 1950  
 Presumy After Paint*

*4 days*

**Estimate Repair Cost to Vehicle No :SCZ262M**

| Description   | Quantity | List Price          | Amount     |
|---|----------|---------------------|------------|
|   |          | <u>S\$</u>          | <u>S\$</u> |
| <b>SPARE PARTS</b>  |          |                     |            |
| 1 REAR WINDSCREEN MOULDING TOP  | 1 PC     | <i>Ne</i> 32.10     | <i>—</i>   |
| 2 REAR WINDSCREEN MUOLDING LH & RH  | 2 PC     | <i>Ne</i> 64.20     | <i>—</i>   |
| 3 REAR WINDSCREEN MOULDING BTM  | 1 PC     | <i>Ne</i> 32.10     | <i>—</i>   |
| 4 TAILGATE  | 1 PC     | <i>Pa</i> 741.50    | <i>✓</i>   |
| 5 TAILGATE VEZEL LOGO   | 1 PC     | <i>Ne</i> 43.20     | <i>—</i>   |
| 6 TAILGATE LOCK   | 1 PC     | <i>R</i> 157.20     | <i>X</i>   |
| 7 TAILGATE LOCK CATCH   | 1 PC     | <i>R</i> 27.70      | <i>X</i>   |
| 8 TAILGATE RUBBER   | 1 PC     | <i>Ne</i> 96.80     | <i>X</i>   |
| 9 TAILGATE INNER TRIMBOARD  | 1 PC     | <i>Sm</i> 153.70    | <i>X</i>   |
| 10 REAR BUMPER  | 1 PC     | <i>Pa</i> 532.10    | <i>—</i>   |
| 11 REAR BUMPER CORNER RH  | 1 PC     | <i>Sm</i> 195.20    | <i>X</i>   |
| 12 REAR BUMPER REFLECTOR RH   | 1 PC     | <i>Sm</i> 178.20    | <i>X</i>   |
| 13 REAR BUMPER SIDE RETAINER RH   | 1 PC     | <i>Sm</i> 17.50     | <i>X</i>   |
| 14 REAR BUMPER CLIPS  | 8 PC     | <i>Ne</i> 28.00     | <i>—</i>   |
| 15 REAR END PANEL   | 1 PC     | <i>R</i> 538.20     | <i>X</i>   |
| 16 REAR END PANEL GARNISH   | 1 PC     | <i>Sm</i> 92.30     | <i>X</i>   |
| 17 REAR KEYLESS ANTENNA   | 1 PC     | <i>Sm</i> 58.10     | <i>X</i>   |
| 18 REAR SMART BUZZER  | 1 PC     | <i>Sm</i> 80.10     | <i>X</i>   |
|   |          | 3,068.20            |            |
|   | Less 20% | 613.64              | 2,454.56   |
| <b>Special Nett</b>   |          |                     |            |
| 19 INNER SEAL   | 1 PC     | <i>Ne</i> 20.00     | <i>—</i>   |
| 20 WINDSCREEN SEALANT   | 1 PC     | <i>Ne</i> 40.00     | <i>—</i>   |
| 21 REVERSE SENSOR   | 1 SET    | <i>Short</i> 200.00 | <i>—</i>   |
| 22 NUMBER PLATE   | 1 PC     | <i>Sm</i> 35.00     | <i>X</i>   |
|   |          | 295.00              | 295.00     |
| <b>LABOUR</b>   |          |                     |            |
| 23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.   | 1 PC     | 120.00              | <i>✓</i>   |
| 24 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.   | 1 PC     | 60.00               | <i>✓</i>   |
| 25 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.   | 1 PC     | 60.00               | <i>50d</i> |
| 26 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.  | 1 PC     | 60.00               | <i>30d</i> |
| 27 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC     | 800.00              | <i>50d</i> |
| 28 TO SPRAY TAILGATE,REAR BUMPER CORNER RH,RR END PANEL.  | 1 PC     | 650.00              | <i>30d</i> |



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

**M/S :** PANG ENG POH  
35 LOR ONG LYE  
#05-07  
SINGAPORE 536443

**Estimate No:** MC1902391  
**Date:** 05 Jan 2022  
**Policy No:** GA238524/1  
**Veh Reg No:** SCZ262M  
**Make/Model:** HONDA VEZEL 1.5X

**ATTN:**  
**Your Ref No:** SCZ262M  
**Claim Type:** Third Party  
**Accident Date:** 03/01/2021  
**TP Veh Reg No:** SKT4709C

## Estimate Repair Cost to Vehicle No :SCZ262M

| Description | Quantity | List Price           | Amount              |
|-------------|----------|----------------------|---------------------|
|             |          | <u>S\$</u>           | <u>S\$</u>          |
|             |          | 1,750.00             | 1,750.00            |
|             |          | Total                | S\$ 4,499.56        |
|             |          | Add GST @ 7%         | 314.97              |
|             |          | Total Amount Payable | <u>S\$ 4,814.53</u> |

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED FOURTEEN AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

**For AH LIM MOTOR COMPANY**

Ah Lim Motor Company

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: