

5a.

5b.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURA	NCE BHD	Ref:	CS/TPS22000132/Kvf3e2	
	C/O Toplis And Ha		Date:	07/03/2022	
	#06-01A, Keck Ser SINGAPORE 0695		Code:	LPC2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLQ 8098J	
	Policy No.	W230305	Coverage (\$)	0.00	
	Claim No.	21/21/22/EC00/002304	Excess (\$)	0.00	
	Assign From	VICTOR FONG	Assign Date	05/01/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 335I (A)	c.c	2979	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	WBA3A92030F095577	Colour	METALLIC RED	
	Odometer	137053 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/35 R19	PIRELLI	9 mm	
	L/H Front Tyre	245/35 R19	PIRELLI	9 mm	
	R/H Rear Tyre	275/30 R19	PIRELLI	9 mm	
	L/H Rear Tyre	275/30 R19	PIRELLI	9 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	19/12/2021	Inspection Date	06/01/2022	
	Survey held at	H C AUTO PTE LTD			

160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722

Remarks

Estimate Days of Repair

4 Working Days

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.