



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22000135/Bqf3s2 Date: 25/04/2022  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJL 8668P	Veh. Inspected	SLQ 7775U
Policy No.		Coverage (\$)	0.00
Claim No.	C10013260/EE	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	05/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA SHUTTLE 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GK81100509	Colour	PURPLE
Odometer	64649 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	4 mm
L/H Front Tyre	195/55 R15	DUNLOP	4 mm
R/H Rear Tyre	195/55 R15	DUNLOP	4 mm
L/H Rear Tyre	195/55 R15	DUNLOP	4 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	22/10/2021	Inspection Date	09/01/2022
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	