

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Supplementary

Vehicle No: SLQ7775U
Model and make: Honda Shuttle

Qty	Parts		List price
1	LH taillamp	S	✓ 520.00 BRV
		S	520.00
		-20% S	104.00
		S	416.00
		Total:	S 416.00

Resurvey
7/1/2022
150 hrs
Tatim Min

Parts 5706.10
@ 20% 1141.22
4564.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: