

ASS. REC. BY:

REF:

EGZ/ 22000139/Kgfb

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

6/1/22 @ 8:15 AM. Car used to 2983.33, 66%

26/1/22 @ 3:47 PM revised to 2250 via Meriden.

Date/Time, File Pass to?

1) 26/1/22

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LB.I: (\$

MER-TP

1550

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Veh No:

SLA 8607A

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Hyundai Elantra c.c

1591

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

235620

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHD841CM-HU099778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/35R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

2

mm

R/Bal.

P

mm

L/Bal.

2

mm

L/Bal.

P

mm

D.O.A.

30/12/21

D.O.I.

5/1/202

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 Fax: 6481 5727 e-mail : ngsmotorsportpteltd@gmail.com

Reg No: 201812604N

4/1/2022

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Attn: Motor Claims Dept

RE: Accident On 30/12/2021 @16:25hrs
Along CTE Towards Moulmein Exit, SLA8607A/SMQ5682E
Claims against SMQ5682E

We submit herewith our direct claim estimate quotation as follows:
Replacement parts - Hy Elantra

1 pc Rear Boot Lid
1 pc Rear Bumper
1 pc Rear Reinforcement
1 pc Lower granish, Rr Bumper
2 pcs Retainer, Rr bumper RH/LH
2 pcs Reflector RH/LH
1 pc End Panel

1 pc Rear Boot "BADGE" S.Net
1 pc Emblem "ELANTRA" S.Net
1 pc Reverse Sensor S.Net

To remove rear damaged parts with all necessary components/
attachments. Straighten chassis member, repair/reshape dented
body panel in accordance with factory specifications..
Replace/reposition damaged parts, refit align into Refix all
necessary components/attachment.

Spray painting

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Notified
11 Dec @ 1550h
Henry After Rain
3 days

R \$ 1,782.40 X
Bumper \$ 491.60 ✓
Rr \$ 330.90 ✓
D.R \$ 272.85 ✓
S \$ 47.40 \$ 94.80 X
\$ 48.40 \$ 96.80 ✓
\$ 397.50 X
\$ 3,466.85
Less 20% \$ (693.37)
R \$ 31.05 ✓
R \$ 48.80 ✓
Shan \$ 280.00 200h
\$ 800.00 300h

\$ 600.00 400h
\$ 4,533.33