

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60488
Date Estimated : 03/01/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Siew Mun Chueng, Dominic (Xiao Wenj
62 Choa Chu Kang Avenue 5
#12-08

Singapore 688192

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNC1573A	WBA12AK0507J49557	30/09/2021	218i Gran Coupe	16

DESCRIPTION

To replace left wing mirror

To respray left mirror cover

To check electrical wiring system at the front section
for proper function

Sundries.

VALUE

425 - 1,275.00
70 - 74.00
168 - 177.00
40.00

Total Labour 1: 1,566.00

DESCRIPTION

LH OUTSIDE MIRROR HEATED WIT
LH MIRROR GLASS HEATED WIDE
LH OUTSIDE MIRROR COVER CAP PRIMED

QTY	PRIC	VALUE
1	822.50	822.50
1	416.95	416.95
1	128.10	128.10

Total Parts : 1,367.55

Store (LKK)
16/2/22, 12.30p

WZ AL
PIP
AL 2
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- Any damaged part(s) during resurvey
- are subject to confirmation
- Survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Any item(s) must be resurveyed and
- Final approval from Insurance Company



Acknowledged by Repairer

Labour 1	:	1,566.00
Parts	:	1,367.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	205.35
Grand Total	:	3,138.90

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **