

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000142/UTF3N2**Date:** 13/01/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29149830MCY
Claimant Vehicle No :	SMX1041U	Insured Vehicle No :	SME3034C
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	639601

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1041U		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4032993
Reg. Date:	15/06/2016 (Man. Year: 2016)	Chassis No:	RU11112988
Colour:	Blue	Odometer:	43711 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,593.12	0.00	3,593.12	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	300.00	2,400.00	88.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,293.12	300.00	5,993.12	95.23

INSPECTION

Date of Assignment:	05/01/2022	Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE Singapore 417808
Date Inspected:	05/01/2022 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2022)

Parts: 144 HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX1041U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-LH	Repair	1,485.70 FL	*- FL
2	1		*FRONT DOOR RUBBER	Not Necessary	152.70 FL	*- FL
3	1		*FRONT DOOR SIDE MIRROR	Not Necessary	845.50 FL	*- FL
4	1		*FRONT DOOR OUTER MOULDING	Not Necessary	199.00 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE	Not Necessary	192.00 FL	*- FL
6	1		*REAR DOOR-LH	Not Necessary	1,485.70 FL	*- FL
7	1		*REAR DOOR RUBBER	Not Necessary	130.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,491.40	0.00
- List Item Discount on L Items 20.00/20.00% (\$)	898.28	0.00
Total Parts (\$)	3,593.12	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	0.00
2	TO APPLY UNDERCOATING	New	100.00	0.00
3	PANEL BEATING	New	1,200.00	100.00
4	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,000.00	200.00
Gross Labour Cost (\$\$)			2,700.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >