

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 11 Jan 2022

Preliminary Advice

Insured Vehicle No : SME3034C
TP Vehicle No : SMX1041U
Make : HONDA VEZEL
Date of Inspection : 05/01/2022
Inspection At : ZOOM AUTO WERKS - KAKI BUKIT (HQ)
BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE
SINGAPORE 417808
Accident Date : 29/11/2021
Assignment Date : 05/01/2022
Est. Duration of Repair : 2

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,293.12
Revised Amount	:S\$	300.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	300.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	28,013.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,987.00

Remarks

- () The vehicle is economical for repair
() The vehicle is not economical for repair
() Part-by-Part repair
() Lump Sum repair

(x) The above survey was conducted on a 'without prejudice' basis.