



**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

**Date Generated : 19/01/2022**
**User ID                      PohSuan**
**Section A - Accident Details**

Registration Number	SHB5633K
Case Reference Number	TAX/01/22/2004
Registration Date	30/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG KOON TEE
Type of Accident	Head to Rear
Accident Date and Time	2/1/2022 6:25 AM
Accident Reported Date and Time	3/1/2022 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113559
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	4/1/2022 8:56 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,116.00	\$200.00
Total Spare Part Cost	\$3,836.14	\$1,205.54
Total Other Cost	\$656.88	(\$55.54)
<b>TOTAL COST</b>	<b>\$6,116.02</b>	<b>\$1,550.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	<b>Ang Bang Kien</b>	<b>GUO QIANG (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>10/01/2022 11:21 AM</b>	<b>10/01/2022 10:41 AM</b>
Signature		
Remarks	Total number of repair days = 3days. SUP = 0 day.	LUMP SUM REPAIR / AFTER PAINT PHOTO.

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2201-0293	<b>Invoice Number</b>	
<b>Quotation Date</b>	19.01.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,116.00</b>	<b>\$200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Lump Sum Adjustment by Surveyor	\$0.00	(\$392.42)
<b>Total Other Costs</b>	<b>\$656.88</b>	<b>(\$55.54)</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check

✓  
X  
✓  
✓  
✓  
✓  
✓  
✓  
X  
X  
✓  
✓  
X  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/01/2022

User ID                      PohSuan

		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
		58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$891.20	0.00	\$0.00	Replace	Not Given	X
		75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X
		75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X
		75403480 10	EMBLEM SUB-ASSY REAR	0.00	\$46.30	0.00	\$0.00	Replace	Not Given	X
			STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>					<b>\$4,433.90</b>		<b>\$786.46</b>			

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
<b>Total</b>					<b>498.80</b>		<b>419.10</b>		

	1,205.56	
+	200.00	
+	536.88	L/S \$1,550/-
	1,942.44	
	-20%	
	1,553.95	