



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 5069S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEADLAMP RH (WCP)	CUT	480.00	480.00
1	FRONT FENDER RH (WCP)	DENTED	170.00	160.00
1	FRONT FENDER SHIELD RH (WCP)	DEFORMED	42.00	40.00
10	FRONT FENDER SHIELD CLIP @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	FRONT BUMPER (WCP)	DEFORMED	260.00	250.00
1	FRONT BUMPER LOWER (WCP)	CRACKED	125.00	120.00
1	FRONT BUMPER FOGLAMP COVER RH (WCP)	CUT	26.00	10.00
1	FRONT BUMPER LAMP RH (WCP)	CUT	80.00	65.00
1	FRONT BUMPER SIDE RETAINER RH (WCP)	NOT NECESSARY	15.00	-
10	FRONT BUMPER CLIP @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	FRONT SHOCK ABSORBER RH (WCP)	NOT NECESSARY	115.00	-
1	FRONT SHOCK ABSORBER MOUNTING (WCP)	NOT NECESSARY	55.00	-
1	FRONT KNUCKLE ARM RH (WCP)	NOT NECESSARY	165.00	-
1	FRONT KNUCKLE BEARING RH (WCP)	NOT NECESSARY	150.00	-
1	FRONT LOWER ARM RH (WCP)	NOT NECESSARY	130.00	-
1	FRONT STABILIZER LINK RH (WCP)	NOT NECESSARY	35.00	-
1	FRONT BUMPER SIDE AIR GRILLE RH (WCP) (ADDITIONAL)	DEFORMED	30.00	30.00
	COST PLUS 10%		191.80	119.50
			2,109.80	1,314.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT TYRE RH (SN)	NOT NECESSARY	220.00	-
1	FRONT RIM (SN)	NOT NECESSARY	400.00	-
			620.00	-
<b><u>LABOUR</u></b>				
	TO CHECK WIRING SYSTEM.		30.00	30.00
	TO CHECK ALIGNMENT.		80.00	80.00
	TO REMOVE / REFIT FRONT UNDERCARRIAGE RH.	NOT NECESSARY	180.00	-
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		650.00	500.00
	SPRAYPAINTING CHARGES.		550.00	400.00

Report Ref No. CS/SMO22000151/Avf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR / BALANCE REAR RH RIM. (ADDITIONAL)		150.00	150.00
			1,640.00	1,160.00
GRAND TOTAL			4,369.80	2,474.50
RECOMMENDED COST OF REPAIRS				2,474.50

Report Ref No. CS/SMO22000151/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.