

簡福星摩哆工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623
VEHICLE NO. : SMN5069S
ACCIDENT DATE : 04-01-2022 18:20
THIRD PARTY REF. : SMD861G

INVOICE NO : TEST
DATE : 10-02-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE SMN5069S KIA CERATO 1.6 (A) LX

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT HEADLAMP RH	480.00
1	FRONT FENDER RH	160.00
1	FRONT FENDER SHIELD RH	40.00
10	FRONT FENDER SHIELD CLIP @\$2.00	20.00
1	FRONT BUMPER	250.00
1	FRONT BUMPER LOWER	120.00
1	FRONT BUMPER FOGLAMP COVER RH	10.00
1	FRONT BUMPER LAMP RH	65.00
1	FRONT BUMPER SIDE AIR GRILLE RH	30.00 *
10	FRONT BUMPER CLIP@\$2.00	20.00
		1,195.00
	ADD 10 %	
		119.50
	TOTAL (A)	
		1,314.50

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO CHECK ALIGNMENT	80.00
1	To repair & Balance rim	150.00 *

VEHICLE NO. : SMN5069S
ACCIDENT DATE : 04-01-2022 18:20
THIRD PARTY REF. : SMD861G

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	500.00
1	SPRAYPAINTING CHRGES	400.00
TOTAL (D)		<u>1160.00</u>
TOTAL REPAIR COST :		<u>2474.50</u>
G S T % :		<u>173.21</u>
INVOICE AMOUNT :		<u>2647.71.</u>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

SOMPO INSURANCE (S) PTE LTD

DATE : 05-01-2022

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWER

SINGAPORE 048623

VEHICLE NO. : SMN5069S

ACCIDENT DATE : 04-01-2022 18:20

THIRD PARTY REF. : SMD861G

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMN5069S KIA CERATO 1.6(A) LX

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)	
1	1 FRONT HEADLAMP RH <i>lit</i>	380.00	✓ 480
2	1 FRONT FENDER RH <i>Dented</i>	170.00	✓ 160
3	1 FRONT FENDER SHIELD RH <i>Deh d</i>	42.00	✓ 40
4	10 FRONT FENDER SHIELD CLIP@2.00 <i>in</i>	20.00	✓
5	1 FRONT BUMPER <i>Deh d</i>	260.00	✓ 250
6	1 FRONT BUMPER LOWER <i>cut</i>	125.00	✓ 120
7	1 FRONT BUMPER FOGLAMP COVER RH <i>cut</i>	26.00	✓ 10
8	1 FRONT BUMPER LAMP RH <i>lit</i>	80.00	✓ 65
9	1 FRONT BUMPER SIDE RETAINER RH ?	15.00	✓
10	10 FRONT BUMPER CLIP@2.00 <i>in</i>	20.00	✓
11	1 FRONT SHOCK ABSORBER RH ?	115.00	✓
12	1 FRONT SHOCK ABSORBER MOUNTING ?	55.00	✓
13	1 FRONT KNUCKLE ARM RH ?	165.00	✓
14	1 FRONT KNUCKLE BEARING RH ?	150.00	✓
15	1 FRONT LOWER ARM RH ?	130.00	✓
1	1 FRONT STABILIZER LINK RH ?	35.00	✓
		1,788.00	
ADD 10 %		178.80	
TOTAL (A)		1,966.80	

SPECIAL NETT ITEMS

1	1 FRONT TYRE RH <i>in</i>	220.00	✓
2	1 FRONT RIM <i>lit</i>	400.00	✓
TOTAL (C)		620.00	

LABOUR CHARGES

1	1 TO CHECK WIRING SYSTEM	30.00	✓
---	--------------------------	-------	---



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SMN5069S
ACCIDENT DATE : 04-01-2022 18:20
THIRD PARTY REF. : SMD861G

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
2	1	TO CHECK ALIGNMENT	80.00 ✓
3	1	TO REMOVE/REFIT FRONT UNDERCARRIAGE RH	180.00 7
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	650.00 500
5	1	SPRAYPAINTING CHRGES	550.00 400
TOTAL (D)			1,490.00
ESTIMATE TOTAL			4,076.80

Admin ling.
P/P 06/04/22
05 Days.
96893735.

Authorized Repairs
Excon Waived, fl.g.



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: gyan@kanfs.net/ patricia@kanfs.net

SOMPO INSURANCE (S) PTE LTD

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWER

SINGAPORE 048623

DATE: 15/3/2022

VEHICLE NO. : SMN5069S
ACCIDENT DATE : 04-01-2022 18:20
THIRD PARTY REF. : SMD861G

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMN5069S KIA CERATO 1.6 (A) LX

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER SIDE AIR GRILLE RH	30.00
			30.00
		ADD 10%	3.00
		TOTAL (A)	33.00
LABOUR CHARGES			
1	1	TO REPAIR/ BALANCE REAR RH RIM	150.00
		TOTAL (C)	150.00
		SUPPLEMENTARY TOTAL	183.00