



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaka Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: ryan@kanfs.net/ patricia@kanfs.net

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

DATE: 15/3/2022

VEHICLE NO. : SMN5069S
ACCIDENT DATE : 04-01-2022 18:20
THIRD PARTY REF. : SMD861G

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMN5069S KIA CERATO 1.6 (A) LX

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER SIDE AIR GRILLE RH <i>Defaced.</i>	30.00 ✓
			30.00
		ADD 10%	3.00
		TOTAL (A)	33.00
			150.00 ✓
		TOTAL (C)	150.00
		SUPPLEMENTARY TOTAL	183.00

LABOUR CHARGES

1 1 TO REPAIR/ BALANCE REAR RH RIM

Adrian Ling
[Signature]