



Case Details

Case Reference Number :

TAX/01/22/2005

Type of Repair : Accident Repair

Vehicle Registration Number : SHF49J

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-17114-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 02/01/2022 06:30 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.1	Replace	✓ R/S
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace	✓ R/S
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair	✓ Repair
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	✓
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	✓ R/S
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	✓
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0	Not Give	✓
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓
Total Spare Part Cost									4,141.13	Surveyor Total 1,303.28				✓
Lump Sum Discount (%)									20.00	Lump Sum Discount 20				
Final Spare Part Cost									3,312.90	Final Sur Total 1,042.02				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY VIEW MIRROR	180.00	80	✓
2	Main	TO RESPRAY FRONT BUMPER	378.00	200	✓
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	✓
4	Main	TO RESPRAY RIM	180.00	0	X <i>nn</i>
Total:			1,116.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	<i>nn</i>
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
3	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			436.00	0.00	680

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,312.90	1,042.62
Total Labour Cost	507.00	200.00
Total Spray Painting	1,116.00	480.00
Other	436.00	0.00
Overall Total	5,371.90	1,722.62
Lump Sum Repair Option	7263.54	1983.28
		☑ -20%: 1600

2022, 16:19

<https://vacswb.smr.com.sg/Estimation.aspx>

Estimator Assessment(\$)

Surveyor Assessment(\$)

Lump Sum Total

5,350.00

1,700.00

Surveyor Approved Amount

1,700.00

No of Repair Days*

5

3

Remarks

LUMP SUM REPAIR / AFTER PAINT PHOTO .

Surveyor Name

GuoQiang

Signature



Save

Clear

Survey Date

04/01/2022