

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/01/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHF49J
Case Reference Number	TAX/01/22/2005
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HO TIEN LOONG LIONEL (HE TIANLONG)
Type of Accident	Side Swipe
Accident Date and Time	3/1/2022 2:30 AM
Accident Reported Date and Time	3/1/2022 12:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113563
Special Instruction to ARC,if any	TP /TOWED \$40/ RIGHT PORTION
Prepared Date and Time	3/1/2022 4:08 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,116.00	\$480.00
Total Spare Part Cost	\$4,141.13	\$1,303.28
Total Other Cost	\$436.00	(\$383.28)
TOTAL COST	\$6,200.13	\$1,600.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / NTUC
ARC / Surveyor Sign Off Date	04/01/2022 5:36 PM	04/01/2022 4:19 PM
Signature		
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2201-0140	Invoice Number	
Quotation Date	13.01.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$383.28)
Total Other Costs	\$436.00	(\$383.28)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8791047450	MIRROR ASSY, OUTER REAR VIEW , RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	25.00	\$67.13	Replace	Replace
		5211947962	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		5380147080	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
Total					\$5,204.54		\$1,303.28		

√
√
R
X
R
X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,303.28	
200.00	
480.00	L/S \$1,600/-
1,983.28	
-20%	
1,586.62	